Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: 12 Jul 2023 Jenny Lew Date:

Preliminary Advice

Insured Vehicle No : XE253B

TP Vehicle No : YM1907M Accident Date : 10/12/2022 Make : ISUZU FTR33P **Assignment Date** : 15/12/2022 Date of Inspection : 21/02/2023 Est. Duration of Repair : Lorry -8 + TMA -5

: THIAM HENG HUAT PTE LTD (SIN MING) Inspection At

176 SIN MING DRIVE, #05-14

SINGAPORE 575721

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gros	:S\$	115,230.00 (Lorry \$20,230.00 + TMA

\$95,000.00)

85,050.00 (Lorry LS \$8,000.00 + TMA **Revised Amount** :S\$ \$77,050.00)

Check Items (Estimated) :S\$ 0.00 Total :S\$ 85,050.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

(

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly	/
		let us have your authorisation.	

 The vehicle is uneconomical to be repaired, you are advised to invite tender for 	for the wreck	۲.
--	---------------	----

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to consistency check, part prices and labour cost.