

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012576/UQP3Q2**Date:** 17/03/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00001132206
<b>Claimant Vehicle No :</b>	YN4692G	<b>Insured Vehicle No :</b>	XE253B
Date of Loss:	10/12/2022	Nature of Claim: TP	Claim No: SNM22D208924/C03/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>YN4692G</b>	Engine No:	4P10B01710
Make & Model:	MITSUBISHI CANTER, 3.0 D (A)	Chassis No:	FEB21EA00159
Reg. Date:	02/01/2014 (Man. Year: 2013)	Odometer:	292915 km
Colour:	White		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,414.00	3,706.40	5,707.60	60.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,680.00	1,320.00	2,360.00	64.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,094.00</b>	<b>5,026.40</b>	<b>8,067.60</b>	<b>61.61</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,000.00</b>		
<b>(\$\$)</b>	13,094.00	4,000.00	9,094.00	69.45
<b>+ GST 8.00/8.00% (\$\$)</b>	1,047.52	320.00	727.52	69.45
<b>Nett Amount (\$\$)</b>	<b>14,141.52</b>	<b>4,320.00</b>	<b>9,821.52</b>	<b>69.45</b>

**INSPECTION**

Date of Assignment:	15/12/2022		
Date Inspected:	21/02/2023	Inspected At:	Thiam Heng Huat Pte Ltd (SIN MING) 176 SIN MING DRIVE, #05-14 Singapore 575721
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Mar 2023)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YN4692G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DECK WOODEN FENCE (O/S)	Cracked	585.00 FS	*380.00 FS
2	1		*CANOPY FRAME	Repair	1,800.00 FL	*- FL
3	1		*CANOPY CANVAS COVER	Torn	315.00 FS	*300.00 FS
4	1		*O/S REAR CABIN PANEL	Dented	750.00 FL	*750.00 FL
5	1		*O/S SIGNAL LAMP TOP	Cracked	780.00 FL	*245.20 FL
6	1		*O/S FRONT CORNER LAMP	Cracked	280.00 FL	*160.00 FL
7	1		*O/S WING MIRROR ASSY	Broken	850.00 FL	*280.00 FL
8	1		*O/S WIND GUARD	Repair	550.00 FL	*- FL
9	1		*O/S PETROL TANK SIDE BEAM	Repair	750.00 FL	*- FL
10	1		*PETROL TANK	Not Necessary	1,200.00 FL	*- FL
11	1		*WOODEN RAILING	Cracked	450.00 FS	*450.00 FS
12	1		*SIDEGATE O/S	Dented / Dented	2,000.00 FL	*2,000.00 FL
					Sub Total (\$\$)	10,310.00 4,565.20
					- List Item Discount on L Items 10.00/25.00% (\$\$)	896.00 858.80
					Total Parts (\$\$)	9,414.00 3,706.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR & MISC CHARGES REPAIR RH DECK PANEL ,RH LOWER BEAM ,HINGES ETC	New	2,000.00	800.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	500.00
3	WIRING	New	60.00	20.00
4	LABOUR TO DISMANTLE AND INSTALL PETROL TANK	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,680.00</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >