

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7567T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER COVER	SCRATCHED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	CUT	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER REINFORCEMENT BRACKET LH RH @ \$138.10	NOT NECESSARY	276.20	-
1	ANTENNA SMARTKEY	NOT NECESSARY	40.50	-
1	REAR BUMPER FOG LAMP	CRACKED	201.50	201.50
	LESS 20% DISCOUNT		-369.13	-226.83
			1,476.52	907.32
	NETT ITEMS			
1	REAR NUMBER PLATE WITH TRIM COVER (N)	MISSING	55.00	55.00
1	REAR BUMPER REVERSE SENSOR (N)	CRACKED	180.00	180.00
	LESS 10% DISCOUNT		-	-23.50
			235.00	211.50
	SPECIAL NETT ITEMS			
1	RENEW ADVERTISEMENT STICKER (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			250.00	250.00
	<u>LABOUR</u>			
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	30.00
			780.00	630.00
	GRAND TOTAL		2,741.52	1,998.82





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,600.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC22012579/Sqp3m4

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**