

ANNEX ARECOMMENDED PARTS

NO	DESCRIPTION OF PARTS	QTY	CONDITIONS	REPAIRER'S AMOUNT	ADJUSTER'S AMOUNT
1	REAR BUMPER ASSY	1	Deformed	\$ 602.60	\$ 602.60 ✓
2	REAR BUMPER SIDE RETAINER	1	Cracked	\$ 106.40	\$ 106.40 ✓
3	REAR BUMPER BRACKET X ^{an}	1	Cracked	\$ 89.20	\$ 89.20 X
4	REAR BUMPER REFLECTOR X ^{an}	1	Grazed	\$ 125.70	\$ 125.70 X
5	REAR BUMPER REINFORCEMENT	1	To Repair	\$ 378.60	-
6	REAR END PANEL	1	To Repair	\$ 727.70	-
7	REAR FENDER LH	1	Buckled	\$ 1,244.80	\$ 1,244.80 986.80
8	REAR FENDER INNER PANEL LH	1	To Repair	\$ 423.20	-
9	REAR FENDER AIR VENT LH	1	Nec	\$ 178.80	\$ 178.80 123.90
10	REAR DOOR ASSY LH	1	To Repair	\$ 1,347.20	-
11	TAILLAMP PANEL LH Repair	1	Buckled	\$ 120.50	\$ 120.50 XR
12	TAILLAMP LH	1	Broken	\$ 410.80	\$ 410.80 368.34
13	BOOTLID ASSY	1	To Repair	\$ 852.90	-
14	BOOTLID LOGO X ^{an}	1	Nec	\$ 68.60	\$ 68.60 X
15	REAR WHEEL RIM LH	1	Cut	\$ 2,173.50	\$ 2,173.50 5/N-300
16	REAR WHEEL BEARING ASSY	1	Jammed	\$ 1,039.90	\$ 1,039.90 637.41
17	SIDE MIRROR ASSY LH	1	Broken	\$ 1,360.50	\$ 1,360.50 981.55

3806.97

259

2855.22

Less 25%

Sub Total :

\$ 11,250.90	\$ 7,521.30
\$ 2,812.72	\$ 1,889.32
\$ 8,438.18	\$ 5,640.98

5/N-300

SPECIAL NETT

18 FRONT BUMPER CLIPS	Set	Nec	\$ 50.00	\$ 50.00 30
19 REAR FENDER INNERSHIELD CLIPS	Set	Nec	\$ 50.00	\$ 50.00 30
20 REAR TYRE LH 708	1	Cut	\$ 150.00	\$ 120.00 80
21 REAR END PANEL SEALANT X ^{an}	2	Nec	\$ 60.00	\$ 60.00 X
22 REAR TAILLAMP PANEL SEALANT X ^{an}	1	Nec	\$ 40.00	\$ 30.00 X
23 REAR FENDER SEALANT	2	Nec	\$ 60.00	\$ 60.00 30
24 REAR WINDSCREEN GLASS SEALANT	2	Nec	\$ 60.00	\$ 60.00 30

Sub Total :

\$ 470.00	\$ 430.00
-----------	-----------

Total Parts:

\$ 8,908.18	\$ 6,070.98
-------------	-------------

204

ANNEX B

RECOMMENDED LABOURS

NO	DESCRIPTION OF JOBS	REPAIRER'S AMOUNT	ADJUSTER'S AMOUNT
1	TO REMOVE & REPLACE THE DAMAGED PARTS AS LISTED IN ANNEX A, INCLUDING REINSTATEMENTS OF THE NECESSARY ATTACHMENTS & FITTINGS TO FACILITATE REPAIRS, JACK, STRAIGHTEN, PANEL BEAT THE AFFECTED PARTS, CORRECT & REALIGN THE NECESSARY PARTS.	\$ 1,600.00	\$ 1,200.00 <i>800</i>
2	TO PUTTY AND SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	\$ 1,000.00 <i>800</i>
3	TO APPLY ANTI RUST PROOFING ON AFFECTED AREA	\$ 100.00	\$ 100.00 <i>40</i>
4	TO CHECK & RECONNECT WIRING	\$ 60.00	\$ 40.00 <i>X</i>
5	TO CHECK LIGHTING FUNCTION	\$ 60.00	\$ 40.00 <i>30</i>
6	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	\$ 150.00	\$ 120.00 <i>/</i>
7	TO REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR	\$ 120.00	\$ 100.00 <i>60</i>
8	TO REMOVE & INSTALL REAR UPHOLSTERY AND SEAT TO FACILITATE REPAIR	\$ 250.00	\$ 250.00 <i>60</i>
9	TO REMOVE & INSTALL REAR WHEEL BEARING	\$ 100.00	\$ 80.00 <i>60</i>
10	TO CONDUCT WHEEL ALIGNMENT	\$ 100.00	\$ 100.00 <i>60</i>
11	TO REMOVE & INSTALL REVERSE SENSORS	\$ 80.00	\$ 60.00 <i>40</i>
12	TO RE-PROGRAMME & RESET DIAGNOSTIC FAULT CODE	\$ 180.00	\$ 120.00 <i>60</i>
Total Labour :		\$ 3,820.00	\$ 3,210.00 <i>2130</i>

ANNEX C

REPAIR DETAILS

ADJUSTED REPAIR COSTS	REPAIRER'S AMOUNT	ADJUSTER'S AMOUNT
Total Parts Cost:	\$ 8,908.18	\$ 6,070.98
Total Labour Cost:	\$ 3,820.00	\$ 3,210.00
Total Repair Cost:	\$ 12,728.18	\$ 9,280.98
Recommended Lump Sum Repair Cost :	\$	7,400.00

P - 2855.22
9/N - 300.00
5/N - 204.00
L - 2130.00

T - 5489.22
202
4391.37
L/S - \$ 4,400 / 6 days