

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2059H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT COVER+	CUT	1,052.20	1,052.20
1	BRACKET-FR BUMPER SIDE RH	NOT NECESSARY	44.80	-
10	BUMPER COVER CLIP	NECESSARY	22.00	22.00
1	LAMP ASSY-HEAD RH#	NOT NECESSARY	1,388.00	-
1	PANEL-FENDER RH+	BUCKLED	663.00	663.00
1	GUARD ASSY-FRONT WHEEL RH	BROKEN	174.90	174.90
	LESS 20% DISCOUNT		-668.98	-382.42
			2,675.92	1,529.68
	NETT ITEMS			
1	FRT DOOR LOGO CTPL (N)	NECESSARY/CUT	75.00	75.00
1	CAP ASSY-WHEEL HUB (N)	СИТ	217.20	217.20
	LESS 10% DISCOUNT		-29.22	-29.22
			262.98	262.98
	SPECIAL NETT ITEMS			
1	ADVERTISMENT STICKER-DOOR (SN)	NECESSARY	100.00	100.00
1	ADVERTISMENT STICKER-FENDER (SN)	NECESSARY	100.00	100.00
			200.00	200.00
	LABOUR			
	PANEL BEATING.		600.00	560.00
	SPRAYPAINT CHARGE.		750.00	750.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
			1,450.00	1,340.00
	GRAND TOTAL		4,588.90	3,332.66





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	2,650.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. NS/INC22012581/Svp3m4

1/

S MOHAMED IRFAN BIN MOHAMED IQUBAL

**Asst. Automotive Assessor** 

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**