

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22012589/DNY3E2**Date:** 03/04/2023REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29154123ACX

Claimant Vehicle No : SHC7822M**Insured Vehicle No :** XD8450B

Date of Loss: 15/12/2022

Nature of Claim: TP Claim No: 643250

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHC7822M**

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)

Engine No: G4LEKU388843

Reg. Date: 13/02/2020 (Man. Year: 2019)

Chassis No: KMHC851CVLU184289

Colour: Yellow

Odometer: 337465 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,028.90	12,751.62	7,277.28	36.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,940.00	1,840.00	3,100.00	62.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,968.90	14,591.62	10,377.28	41.56
+ GST 8.00/8.00% (S\$)	1,997.51	1,167.33	830.18	41.56
Nett Amount (S\$)	26,966.41	15,758.95	11,207.46	41.56

INSPECTION

Date of Assignment: 16/12/2022

Date Inspected: 16/12/2022 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)
Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Estimated Period of Repair: 7.0 days

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2023)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC7822M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,549.70 FL	*2,549.70 FL
2	1		*BOOT LID RUBBER	Deformed	187.40 FL	*187.40 FL
3	2		*BOOT LID HINGE (LH/RH)	Not Necessary	142.60 FL	*- FL
4	2		*BOOT LID ABSORBER (LH/RH)	Not Necessary	173.40 FL	*- FL
5	1		*BOOT LID LOCK UPPER	Bent / Damaged	224.00 FL	*224.00 FL
6	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
7	1		*EMBLEM-HYBRID	Necessary	24.30 FL	*24.30 FL
8	1		*EMBLEM-IONIQ	Necessary	31.30 FL	*31.30 FL
9	1		*REAR SPOILER	Mtg Cracked	665.40 FL	*665.40 FL
10	1		*THIRD BRAKE LIGHT	Broken	385.60 FL	*385.60 FL
11	1		*BOOT HANDLE	Not Necessary	31.80 FL	*- FL
12	2		*BOOT LID LAMP (LH/RH)	Mtg Cracked	1,644.00 FL	*1,644.00 FL
13	1		*BOOT LID TRIMBOARD	Mtg Cracked	259.70 FL	*259.70 FL
14	10		*BOOT LID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
15	1		*BOOT LID TRIMBOARD, CENTRE	Not Necessary	159.60 FL	*- FL
16	2		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	185.00 FL	*- FL
17	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
18	1		*BOOT LID GLASS, LOWER	Shattered	584.90 FL	*584.90 FL
19	1		*BOOT LID GLASS UPPER MOULDING	Not Necessary	186.30 FL	*- FL
20	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
21	1		*REAR BUMPER	Cracked	459.40 FL	*459.40 FL
22	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	*394.80 FL
23	1		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	O/S Bent / N/S Serviceable	376.20 FL	*188.10 FL
24	1		*ANTENNA ASSY-SMARTK OUTER	Mtg Broken	689.50 FL	*40.50 FL
25	1		*REAR BUMPER CENTRE MOULDING ASSY	Mtg Cracked	451.25 FL	*451.25 FL
26	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Mtg Cracked	155.00 FL	*155.00 FL
27	1		*REAR BUMPER STAY	Not Necessary	138.10 FL	*- FL
28	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Not Necessary	171.60 FL	*- FL
29	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
30	1		*REAR BUMPER UNDER CENTRE	Mtg Cracked	123.85 FL	*123.85 FL
31	2		*REAR BUMPER SIDE UNDER (LH/RH)	Not Necessary	246.20 FL	*- FL
32	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
33	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
34	1		*REAR BUMPER RESERVE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL
35	1		*LICENCE LAMP	Mtg Broken	193.53 FL	*193.53 FL
36	2		*TAIL LAMP (LH/RH)	Mtg Broken	1,870.80 FL	*1,870.80 FL
37	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	417.80 FL	*- FL
38	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
39	1		*ANTENNA ASSY - TRUNK	Mtg Broken	689.50 FL	*40.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR PANEL GARNISH	Deformed	346.80 FL	*346.80 FL
41	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
42	1		*SPARE WHEEL LOCK NUT	Not Necessary	89.50 FL	*- FL
43	1		*SPARE TYRE PANEL	Not Necessary	892.50 FL	*- FL
44	1		*SPARE TYRE PANEL CUSHION	Not Necessary	692.50 FL	*- FL
45	1		*REAR TRAY TOOLS BOX RH	Bent	675.30 FL	*675.30 FL
46	1		*REAR TRAY TOOLS BOX LH	Bent	693.20 FL	*693.20 FL
47	1		*REAR TRAY LUGGS CENTER	Deformed	354.20 FL	*354.20 FL
48	1		*ASSY BSD BLIND SPOT RADAR (LH/RH)	O/SBracketBent/N/SNotNecessary	3,568.80 FL	*1,784.40 FL
49	1		*REVERSE CAMERA ASSY	Not Necessary	983.20 FS	*- FS
50	1		*BOOT LID CITY CAB LOGO & TEL NO STICKER	Necessary	35.00 FS	*35.00 FS
51	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
52	1		*REAR NO. PLATE + TRIM COVER	Dislodged	45.00 FS	*45.00 FS
53	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*92.00 FS
54	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
55	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
56	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
57	1		*SPARE TYRE PANEL TOP COVER SILICON	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,589.83	15,801.53
- List Item Discount on L Items 20.00/20.00% (\$\$)	4,560.93	3,049.91
Total Parts (\$\$)	20,028.90	12,751.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,400.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
7	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
8	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	550.00	150.00
9	DIAGNOSTIC & RESETTING ADAS OPTICAL SENSOR }	New	550.00	0.00
Gross Labour Cost (S\$)			4,940.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >