

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012599/RVP3E2**Date:** 07/02/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00031882200

**Claimant Vehicle
No :** SMD9959A**Insured Vehicle
No :** SNE9994E

Date of Loss: 30/11/2022

Nature of Claim: TP

Claim
No: SNM22D208902/C02/TANCHCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMD9959A**Make & Model: MERCEDES-BENZ CLA180, 1.6 COUPE URBAN
(R18 LED) (A)

Engine No: 27091031811995

Reg. Date: 20/03/2019 (Man. Year: 2018)

Chassis No: WDD1173422N747364

Colour: Blue

Odometer: 67314 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,026.80	1,820.06	206.74	10.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,620.00	2,260.00	1,360.00	37.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,646.80	4,080.06	1,566.74	27.75
+ GST 7.00/7.00% (S\$)	395.28	285.60	109.68	27.75
Nett Amount (S\$)	6,042.08	4,365.66	1,676.42	27.75

INSPECTION

Date of Assignment: 03/01/2023

Date Inspected: 30/01/2023 Inspected At:

Cycle & Carriage Industries Pte Ltd (Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Feb 2023)

Parts: 143 MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD9959A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,252.41 FS	*1,252.41 FS
2	1		*REAR BUMPER LOWER TRIM	Scratched	358.12 FS	*358.12 FS
3	1		*CTR/ REAR BUMPER MOULDING	Necessary	209.53 FS	*209.53 FS
4	1		*LH/ REAR BUMPER MOUNTING RAIL	Not Necessary	33.02 FS	*- FS
5	1		*RH/ REAR BUMPER MOUNTING RAIL	Not Necessary	40.96 FS	*- FS
6	1		*CTR/ BASIC MOUNTING FOR BUMPER	Not Necessary	132.76 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) **2,026.80** **1,820.06**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	960.00
2	RESPRAY REAR BUMPER	New	1,200.00	800.00
3	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
Gross Labour Cost (\$\$)			3,620.00	2,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >