

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012600/UQP3Q2**Date:** 28/12/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00038572202		
Claimant Vehicle No :	SGP2226K	Insured Vehicle No :	SKR4339Y		
Date of Loss:	11/12/2022	Nature of Claim:	TP	Claim No:	SNM22D208925/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGP2226K	Engine No:	HRA2570424A
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT (A)	Chassis No:	SJNFEAJ11U2192276
Reg. Date:	26/03/2018 (Man. Year: 2017)	Odometer:	23493 km
Colour:	Brown		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,958.90	2,778.59	1,180.31	29.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,650.00	630.00	27.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,238.90	4,428.59	1,810.31	29.02
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	6,238.90	3,500.00	2,738.90	43.90

INSPECTION

Date of Assignment:	21/12/2022	
Date Inspected:	19/12/2022 Inspected At:	H S Automotives Pte Ltd (HQ) BLK 2 KAKI BUKIT AVENUE 2 #01-15 KAKI BUKIT AUOTHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts: M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGP2226K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	846.50 F	*846.50 FL
2	1		*REAR BUMPER RETAINER L/R	N/S Bent	55.60 F	*27.80 FL
3	1		*REAR BUMPER CLIP	Necessary	35.00 F	*35.00 FL
4	1		*REAR BUMPER SPONGE	Torn	155.60 F	*155.60 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	746.20 F	*746.20 FL
6	4		*REAR BUMPER REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
7	1		*REAR WHEEL ARC GARNISH LH	Torn	480.20 F	*480.20 FL
8	1		*REAR TAIL LAMP LH	Not Necessary	381.20 F	*- FL
9	1		*REAR TAIL LAMP LOWER BRACKET LH (NPA)	Not Necessary	0.00 F	*- FL
10	1		*REAR END PANEL	Dented	573.80 F	*573.80 FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	298.60 F	*- FL
12	1		*REAR END PANEL GARNISH CLIP	Not Necessary	20.00 FS	*- FS
13	1		*REAR END PANEL WEATHERSTRIP	Not Necessary	166.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,958.90	3,065.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	286.51
Total Parts (\$\$)	3,958.90	2,778.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,000.00	900.00
2	SPRAY PAINT	New	1,000.00	600.00
3	RUST PROOF	New	80.00	40.00
4	TO INSTALL REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE/REFIX REAR EXHAUST PIPE	New	100.00	60.00
Gross Labour Cost (\$\$)			2,280.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >