

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22012606/DQY3E2**Date:** 29/05/2023REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SJN8767B **Insured Vehicle No :** SDK1984Z
 Date of Loss: 14/12/2022 Nature of Claim: TP Claim No: EL REF: DMPC2200632H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN8767B**
 Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 3ZZ4860018
 Reg. Date: 02/03/2009 (Man. Year: 2009) Chassis No: MR053ZEE106139211
 Colour: Blue Odometer: 160159 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 1,426.17 | 539.67 | 886.50 | 62.16 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,510.00 | 420.00 | 1,090.00 | 72.19 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 2,936.17 | 959.67 | 1,976.50 | 67.32 |
| Approved Total (Overridden) (\$\$) | | 700.00 | | |
| (\$\$) | 2,936.17 | 700.00 | 2,236.17 | 76.16 |
| + GST 8.00/8.00% (\$\$) | 234.89 | 56.00 | 178.89 | 76.16 |
| Nett Amount (\$\$) | 3,171.06 | 756.00 | 2,415.06 | 76.16 |

INSPECTION

Date of Assignment: 16/12/2022
 Date Inspected: 28/12/2022 Inspected At: Supreme Auto Service Pte Ltd (HQ)
 176 Sin Ming Drive #02-01, Sin Ming Autocare
 Singapore 575721
 Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 29 May 2023) |
| Parts: | 143 | TOYOTA COROLLA 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJN8767B) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|----------------------------|---------------|------------|--|
| 1 | 1 | | *REAR BUMPER | Mtg Broken | 452.90 FL | *452.90 FL |
| 2 | 2 | | *REAR BUMPER BRACKET | Not Necessary | 166.80 FL | *- FL |
| 3 | 4 | | *REAR BUMPER CLIPS | Not Necessary | 12.00 FL | *- FL |
| 4 | 1 | | *REAR BUMPER BEAM | Serviceable | 172.30 FL | *- FL |
| 5 | 2 | | *REAR BUMPER SIDE RETAINER | Not Necessary | 86.00 FL | *- FL |
| 6 | 2 | | *REAR BUMPER REFLECTOR | Not Necessary | 152.80 FL | *- FL |
| 7 | 1 | | *REAR END PANEL | Not Necessary | 327.10 FL | *- FL |
| 8 | 1 | | *REAR END PANEL GARNISH | Not Necessary | 185.00 FL | *- FL |
| 9 | 1 | | *SET REVERSE SENSOR | Broken | 260.00 FS | *200.00 FS |
| | | | | | | F=Franchise part. S=SpcNett. L=ListItemDisc. |
| Sub Total (\$\$) | | | | | 1,814.90 | 652.90 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | | | | | 388.73 | 113.23 |
| Total Parts (\$\$) | | | | | 1,426.17 | 539.67 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REPLACE ALL THE PARTS MENTIONED ABOVE, KNOCKING AND STRAIGHTEN UP THE NECESSARY AFFECTED AREAS | New | 600.00 | 200.00 |
| 2 | TO CHECK WIRING SYSTEM | New | 40.00 | 0.00 |
| 3 | TO SPRAY PAINTING ON AFFECTED AREAS | New | 550.00 | 200.00 |
| 4 | TO REMOVE AND REPLACE REVERSER SENSOR | New | 80.00 | 20.00 |
| 5 | TO APPLY RUST PROOFING | New | 120.00 | 0.00 |
| 6 | TO APPLY WATERPROOF SEALANT ON WEILDED PANELS | New | 120.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 1,510.00 | 420.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >