

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012619/AYA3Q2**Date:** 26/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100397324
Claimant Vehicle No :	SJN3539B	Insured Vehicle No :	SKQ7540S
Date of Loss:	27/11/2022	Nature of Claim:	TP
		Claim No:	8473155387SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN3539B	Engine No:	R20A31800473
Make & Model:	HONDA ACCORD, 2.0 (A)	Chassis No:	MRHCP16308P020452
Reg. Date:	12/02/2009 (Man. Year: 2008)	Odometer:	171923 km
Colour:	Grey		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,099.52	2,619.04	3,480.48	57.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	2,000.00	1,100.00	35.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,199.52	4,619.04	4,580.48	49.79
Approved Total (Overridden) (S\$)		3,700.00		
Nett Amount (S\$)	9,199.52	3,700.00	5,499.52	59.78
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,207.45		

INSPECTION

Date of Assignment:	29/11/2022		
Date Inspected:	29/11/2022	Inspected At:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	620.00 FL	*620.00 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Cracked	38.50 FL	*38.50 FL
3	1		*FRONT BUMPER SENSOR LH	Damaged	385.00 FL	*260.00 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	299.90 FL	*- FL
5	1		*FRONT GRILLE CHROME	Not Necessary	198.60 FL	*- FL
6	1		*FRONT GRILLE BASE	Not Necessary	211.80 FL	*- FL
7	1		*FRONT GRILLE HONDA LOGO	Not Necessary	68.00 FL	*- FL
8	1		*FRONT DOOR LH	Repair	1,106.00 FL	*- FL
9	1		*REAR DOOR LH	Repair	907.00 FL	*- FL
10	1		*HEADLAMP LH	Cracked	856.00 FL	*856.00 FL
11	1		*HEADLAMP BULB LH	Damaged	431.40 FL	*180.00 FL
12	1		*HEADLAMP LOWER BRACKET LH	Cracked	79.40 FL	*79.40 FL
13	2		*HEADLAMP CLIP	Not Necessary	16.00 FL	*- FL
14	1		*SUPPORT PANEL	Not Necessary	524.00 FL	*- FL
15	1		*FRONT RESONATOR BOX LH	Cracked	250.00 FL	*250.00 FL
16	1		*WEATHERSTRIP LH	Not Necessary	45.00 FL	*- FL
17	1		*FOG LAMP COVER LH (NPA)	Not Necessary	0.00 FL	*- FL
18	1		*FRONT FENDER LH	Dented	752.00 FL	*687.00 FL
19	1		*FRONT LH WEATHERSTRIP	Not Necessary	55.00 FL	*- FL
20	10		*FRONT BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
21	7		*FRONT GRILLE CLIP	Not Necessary	28.00 FS	*- FS
22	7		*FRONT GRILLE CLIP	Not Necessary	28.00 FS	*- FS
23	1		*FRONT LH WHEEL HOUSE EXTENSION OUTER	Buckled	265.40 FL	*265.40 FL
24	1		*FRONT LH WHEEL HOUSE EXTENSION INNER	Repair	395.40 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,600.40	3,266.30
- List Item Discount on L Items 20.00/20.00% (\$)	1,500.88	647.26
Total Parts (\$)	6,099.52	2,619.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,000.00	600.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	1,200.00	800.00
4	REMOVE AND REPLACE RESONATOR BOX	New	60.00	30.00
5	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	400.00	300.00
6	SPRAY PAINTING AFFECTED ATREAS - WHEEL HOUSE UPPER & LOWER	New	300.00	200.00
7	TO SPRAY UNDERCOATING	New	80.00	40.00
Gross Labour Cost (\$\$)			3,100.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >