

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012622/APA3Q2**Date:** 23/06/2023REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070138733
Claimant Vehicle No : SMY2540J **Insured Vehicle No :** SMV3611Y
 Date of Loss: 07/12/2022 Nature of Claim: TP Claim No: 8401854289SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY2540J**
 Make & Model: TOYOTA RAIZE, 996cc (A) Engine No: 1KR2652386
 Reg. Date: 25/02/2021 (Man. Year: 2020) Chassis No: A200A0038111
 Colour: Black Odometer: 34052 km
 Engine Capacity: 996 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,321.50	7,216.25	3,105.25	30.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	2,560.00	1,770.00	40.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,651.50	9,776.25	4,875.25	33.27
Approved Total (Overridden) (S\$)		7,800.00		
Nett Amount (S\$)	14,651.50	7,800.00	6,851.50	46.76
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,307.45		

INSPECTION

Date of Assignment: 08/12/2022
 Date Inspected: 08/12/2022 Inspected At: YSK Auto Workshop (HQ)
 1 Kaki Bukit Avenue 6 @ AutoBay, #01-71
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	130.00 FL	*- FL
2	1		*REAR BUMPER	Distorted	1,245.00 FL	*1,245.00 FL
3	2		*REAR BUMPER SIDE HOLDER	Not Necessary	168.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	190.00 FL	*- FL
5	1		*REAR BUMPER LOWER SPOILER	Deformed	652.00 FL	*652.00 FL
6	2		*REAR BUMPER SIDE GRILLE	Not Necessary	262.00 FL	*- FL
7	1		*REAR END PANEL	Dented	721.00 FL	*721.00 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	235.00 FL	*235.00 FL
9	1		*REAR END PANEL ANTENNA SENSOR	Damaged	198.00 FL	*198.00 FL
10	2		*REAR END PANEL AIR VENT	Deformed	84.00 FL	*84.00 FL
11	2		*TAILLAMP	Cracked	950.00 FL	*950.00 FL
12	1		*TAILGATE	Distorted	1,580.00 FL	*1,580.00 FL
13	1		*TAILGATE LOCK	Damaged	393.00 FL	*393.00 FL
14	1		*TAILGATE WEATHERSTRIPE	Damaged	355.00 FL	*355.00 FL
15	1		*TAILGATE GLASS MOULDING	Necessary	121.00 FL	*121.00 FL
16	2		*REAR FENDER INNER TRIM BOARD	Deformed	1,090.00 FL	*1,090.00 FL
17	1		*REAR FENDER ARC GARNISH	O/S Deformed	412.00 FL	*206.00 FL
18	1		*SPARE TYRE PANEL	Repair	1,249.00 FL	*- FL
19	1		*SPARE TYRE PANEL TOP BOARD	Deformed	525.00 FL	*525.00 FL
20	1		*REAR EXHAUST PIPE	Not Necessary	615.00 FL	*- FL
21	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	36.00 FL	*- FL
22	2		*REAR EXHAUST PIPE GASKET	Not Necessary	31.00 FL	*- FL
23	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
24	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
25	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
26	1		*REAR BUMPER LOWER SPOILER GARNISH	Deformed	800.00 FS	*500.00 FS
27	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
28	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
29	1		*SET REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
30	1		*SET TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
31	2		*SETS REAR FENDER INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
32	2		*SET REAR FENDER ARC GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
33	1		*SET SPARE TYRE PANEL INSULATION PADS	Not Necessary	280.00 FS	*- FS
34	1		*REAR EXHAUST PIPE COVER (AKRAPOVIC)	Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **13,132.00** **9,305.00**
- List Item Discount on L Items 25.00/25.00% (S\$) 2,810.50 2,088.75

Total Parts (S\$) **10,321.50** **7,216.25**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,600.00	1,100.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	900.00
3	WIRING CHECK	New	100.00	30.00
4	TO APPLY TUFF COAT	New	150.00	100.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO REMOVE VIDEO RECORDER	New	100.00	50.00
8	TO REMOVE UPHOLSTERY & REAR SEAT	New	300.00	80.00
9	TO TRANSFER TAILGATE FITTINGS	New	150.00	80.00
10	TO REMOVE TAILGATE GLASS	New	180.00	120.00
11	TO REMOVE EXHAUST PIPE	New	150.00	0.00
Gross Labour Cost (S\$)			4,330.00	2,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >