

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012623/AYA3Q2**Date:** 17/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700084094
Claimant Vehicle No :	SLL6827L	Insured Vehicle No :	SLU3964X
Date of Loss:	10/12/2022	Nature of Claim:	TP
		Claim No:	3365907164SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLL6827L	Engine No:	2ZR1835183
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE206035384
Reg. Date:	07/03/2017 (Man. Year: 2016)	Odometer:	106217 km
Colour:	Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,639.00	6,403.25	5,235.75	44.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,290.00	2,000.00	3,290.00	62.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,929.00	8,403.25	8,525.75	50.36
Approved Total (Overridden) (S\$)		6,700.00		
Nett Amount (S\$)	16,929.00	6,700.00	10,229.00	60.42
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,307.45		
Global Sum Settlement (S\$)		7,200.00		

INSPECTION

Date of Assignment:	12/12/2022	
Date Inspected:	12/12/2022 Inspected At:	JL Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,340.00 FL	*1,295.00 FL
2	1		*TAILGATE LAMP	N/S Cut	690.00 FL	*345.00 FL
3	1		*TAILGATE LOGO	Necessary	64.00 FL	*64.00 FL
4	1		*TAILGATE MOULDING	Cracked	239.00 FL	*239.00 FL
5	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	128.00 FL	*- FL
6	1		*TAILGATE OUTER BOTTOM SWITCH LOCK	Not Necessary	218.00 FL	*- FL
7	1		*TAILGATE TOP LOCK	Damaged	359.00 FL	*359.00 FL
8	1		*TAILGATE LOCK CATCH	Not Necessary	35.00 FL	*- FL
9	1		*TAILGATE INNER BOARD	Cracked	398.00 FL	*398.00 FL
10	2		*TAILGATE DAMPER	Not Necessary	392.00 FL	*- FL
11	1		*TAILGATE DETECTOR	Cracked	489.00 FL	*189.00 FL
12	1		*TAIL GATE DETECTOR WIREHARNES	Not Necessary	768.00 FL	*- FL
13	2		*TAILGATE STOPPER	Not Necessary	50.00 FL	*- FL
14	1		*TAILGATE WINDSCREEN MOULDING	Necessary	246.00 FL	*246.00 FL
15	1		*TAILLAMP	N/S Cut	794.00 FL	*397.00 FL
16	1		*REAR BUMPER	Distorted	1,167.00 FL	*625.00 FL
17	1		*REAR BUMPER REFLECTOR	N/S Cracked	136.00 FL	*68.00 FL
18	2		*REAR BUMPER SIDE RETAINER (FRONT)	Not Necessary	190.00 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER (REAR)	Necessary	152.00 FL	*152.00 FL
20	2		*REAR BUMPER BRACKET	Dented	210.00 FL	*210.00 FL
21	2		*REAR FENDER INNER COWLING	Not Necessary	494.00 FL	*- FL
22	1		*REAR FENDER INNER TRIM	N/S Cracked	1,444.00 FL	*1,304.00 FL
23	1		*REAR END PANEL	Dented	530.00 FL	*530.00 FL
24	1		*REAR END PANEL TOP GARNISH	Deformed	295.00 FL	*295.00 FL
25	1		*REAR FLOOR PANEL	Repair	742.00 FL	*- FL
26	1		*REAR FLOOR PANEL TOP BOARD	Deformed	598.00 FL	*561.00 FL
27	1		*REAR FLOOR PANEL SIDE BOARD	N/S Cracked	250.00 FL	*125.00 FL
28	1		*REAR FLOOR PANEL TOP BOARD INNER SUPPORT	Not Necessary	360.00 FL	*- FL
29	1		*REAR TOOLS SPONGE	Not Necessary	185.00 FL	*- FL
30	1		*REAR NUMBER PLATE	Cracked	80.00 FS	*60.00 FS
31	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
32	1		*TAILGATE SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*SET TAILGATE OUTER MOULDING CLIP	Necessary	50.00 FS	*20.00 FS
34	1		*SET TAILGATE UPPER TRIM CLIP	Not Necessary	50.00 FS	*- FS
35	1		*SET TAILGATE INNER BOARD CLIP	Necessary	60.00 FS	*30.00 FS
36	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
37	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
38	1		*SET TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
39	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
40	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
41	1		*SET REAR FENDER INNER UPPER TRIM CLIP	Not Necessary	60.00 FS	*- FS
42	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
43	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
44	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	350.00 FS	*- FS
45	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
46	1		*TAILGATE WEATHERSTRIP	Cut	329.00 FL	*329.00 FL
47	1		*TAILGATE EMBLEM VALVE MATIC (SPECIAL TYPE)	Necessary	120.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,962.00	8,336.00
- List Item Discount on L Items 25.00/25.00% (\$)	3,323.00	1,932.75
Total Parts (\$)	11,639.00	6,403.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
8	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
10	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
11	REMOVE AND REFIX FUEL TANK TO FACILIATE FENDER REPLACEMENT	New	120.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			5,290.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >