



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 7992C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	SCRATCHED	595.70	595.70
10	REAR BUMPER CLIPS @ 10PCS @\$4.50	NECESSARY	45.00	45.00
1	REAR BUMPER UPPER CENTER MOULDING (GREY COLOUR)	SCRATCHED	296.50	296.50
1	REAR BUMPER TOW COVER (RHS)	SCRATCHED	35.00	35.00
1	REAR BUMPER REVERSE SENSOR @ 1PC	SCRATCHED	268.00	268.00
1	REAR FENDER OUTER PROTECTOR (RHS)	SCRATCHED	198.50	198.50
1	REAR RIM (RHS)	SCRATCHED	813.50	813.50
5	REAR RIM HUP CAP @ 5PCS @\$48.70	SCRATCHED	243.50	243.50
	LESS 20% DISCOUNT		-499.14	-499.14
			1,996.56	1,996.56
	<u>LABOUR</u>			
	TO REMOVE & REPLACED RHS REAR RIM & CONDUCT WHEEL BALANCING.		100.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO KNOCKING & PANEL BEATING.		600.00	300.00
	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.		600.00	300.00
			1,420.00	710.00
	GRAND TOTAL		3,416.56	2,706.56
	RECOMMENDED COST OF REPAIRS			2,706.56

Report Ref No. CS/SPF22012637/Rny3m4

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,700-\$2,750

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.