

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS3/FCI22012638/Rny3m4
	16 RAFFLES QUA #42-01 HONG LEC 048581	Y ONG BUILDING SINGAPORE	Date:	27/12/2022
			Code:	FCI2
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	XD 6569G	Veh. Inspected	SBJ 82L
	Policy No.	D-22099559MFVS/13	Coverage (\$)	0.00
	Claim No.	D22003993MFVS	Excess (\$)	0.00
	Assign From	AINI BINTE	Assign Date	19/12/2022
2.	Vehicle Particulars & Condition			
	Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	RU11314831	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SU:	STAINED DAMAGES AT THE O/S	REAR PORTION.	
5.	General Information			
	Accident Date	16/12/2022	Inspect Date / Time	19/12/2022 (04:32 PM)
	Survey held at	BING TAT AUTO SERVICE		
		NO.6 PANDAN LOOP SINGAPORE 128224		
5a.	Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/FCI22012638/Rny3m4

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

D)MARKET VALUE:\$92,000.00

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser