

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012640/RQP3Q2**Date:** 12/06/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCNSA00006402201

**Claimant Vehicle No :** SKS7787L **Insured Vehicle No :** SMA7615X

Date of Loss: 09/12/2022 Nature of Claim: TP Claim No: SNM22D209018/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKS7787L**

Make & Model: BMW 318i, 2.0 ADPT LED HL SPORTLINE (A) Engine No: F0413922B48B20A

Reg. Date: 31/08/2021 (Man. Year: 2021) Chassis No: WBA70DY0708B96918

Colour: Blue Odometer: 24266 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,465.60	1,460.10	1,005.50	40.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,767.00	2,252.00	515.00	18.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,232.60</b>	<b>3,712.10</b>	<b>1,520.50</b>	<b>29.06</b>
<b>+ GST 8.00/8.00% (S\$)</b>	418.61	296.97	121.64	29.06
<b>Nett Amount (S\$)</b>	<b>5,651.21</b>	<b>4,009.07</b>	<b>1,642.14</b>	<b>29.06</b>

**INSPECTION**

Date of Assignment: 05/01/2023

Date Inspected: 16/01/2023 Inspected At: Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jun 2023)
Parts:	143	BMW 318i 2.0 ADPT LED HL SPORTLINE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS7787L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR RH LATERAL MOUNT	Not Necessary	205.70 FS	*- FS
3	1		*TRIM STRIP (SPORT)	Not Necessary	96.10 FS	*- FS
4	1		*REAR RH TRIM PANEL	Scratched	99.75 FS	*99.75 FS
5	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	136.30 FS	*- FS
6	1		*REAR BUMPER RH SIDE GUIDE	Not Necessary	136.30 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED (SHORT)	Cut	1,280.35 FS	*1,280.35 FS
8	1		*REAR RH REAR REFLECTOR	Not Necessary	39.80 FS	*- FS
9	1		*DECOUPLING RING	Not Necessary	5.30 FS	*- FS
10	1		*ULTRASONIC SENSOR PHYTONIC BLUE WC1	Not Necessary	386.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	2,465.60 1,460.10

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BUMPER REAR PANEL AND ATTACHMENTS	New	1,275.00	850.00
2	TO SPRAY PAINT BUMPER REAR PANEL	New	1,058.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
5	COATING QUOTATION PROVIDED BY OWNER	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,767.00</b>	<b>2,252.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >