

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012642/UNP3Q2**Date:** 06/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00027932200
Claimant Vehicle No :	SKS3031K	Insured Vehicle No :	YP5535K
Date of Loss:	16/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209059/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS3031K	Engine No:	L15Z12100095
Make & Model:	HONDA MOBILIO SV, 1.5 CVT (A)	Chassis No:	MRHDD4870FP000077
Reg. Date:	06/04/2015 (Man. Year: 2015)	Odometer:	90283 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	APLUS 6 mm	Rear Left Side:	APLUS 6 mm
Front Right Side:	APLUS 6 mm	Rear Right Side:	APLUS 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,541.80	5,959.68	4,582.12	43.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	2,250.00	1,630.00	42.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,421.80	8,209.68	6,212.12	43.07
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	14,421.80	6,500.00	7,921.80	54.93
+ GST 8.00/8.00% (S\$)	1,153.74	520.00	633.74	54.93
Nett Amount (S\$)	15,575.54	7,020.00	8,555.54	54.93

INSPECTION

Date of Assignment:	19/12/2022	
Date Inspected:	19/12/2022	Inspected At: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS3031K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE GLASS	Shattered	1,032.00 FL	*1,032.00 FL
2	1		*TAILGATE GLASS MOULDING	Necessary	188.00 FL	*98.00 FL
3	1		*TAILGATE	Badly Dented	1,359.00 FL	*1,047.00 FL
4	1		*TAILGATE LOGO	Necessary	49.00 FL	*49.00 FL
5	1		*TAILGATE EMBLEM MOBILO	Necessary	48.00 FL	*48.00 FL
6	1		*TAILGATE EMBLEM VTEC	Necessary	38.00 FL	*38.00 FL
7	1		*TAILGATE EMBLEM RS	Necessary	58.00 FL	*58.00 FL
8	1		*TAILGATE OUTER GARNISH	Cracked	297.00 FL	*245.30 FL
9	1		*TAILGATE LOCK	Dented / Jammed	322.00 FL	*202.00 FL
10	1		*TAILGATE LOCK CABLE	Cracked	49.00 FL	*49.00 FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	167.00 FL	*91.10 FL
12	2		*TAILGATE LICENSE PLATE BULB & CASING	Not Necessary	136.00 FL	*- FL
13	1		*TAILGATE UNLOCK HANDEL	Not Necessary	143.00 FL	*- FL
14	1		*TAILGATE INNER TRIM BOARD	Twisted	148.00 FL	*148.00 FL
15	1		*TAILGATE INSULATOR	Not Necessary	89.00 FL	*- FL
16	1		*TAILGATE TOP SPOILER	Repair	582.00 FL	*- FL
17	1		*REAR WIPER MOTOR	Jammed	389.00 FL	*389.00 FL
18	1		*REAR WIPER ARM	Twisted	88.00 FL	*88.00 FL
19	1		*REAR WIPER ARM COVER	Missing	23.00 FL	*23.00 FL
20	1		*REAR WIPER BLADE	Not Necessary	68.00 FL	*- FL
21	2		*TAILGATE LAMP	Cracked / Cut	574.00 FL	*280.00 FL
22	2		*TAILLAMP	Cracked / Cut	772.00 FL	*490.00 FL
23	1		*REAR BUMPER	Dented	663.00 FL	*542.00 FL
24	2		*REAR BUMPER SIDE RETAINER	Necessary	136.00 FL	*50.00 FL
25	1		*REAR BUMPER REFLECTOR	N/S Cut	114.00 FL	*57.00 FL
26	1		*REAR BUMPER CHROME GARNISH	Cut	169.00 FL	*169.00 FL
27	1		*REAR BUMPER CENTER SPACE	Not Necessary	69.00 FL	*- FL
28	2		*REAR BUMPER SPONGE	Torn	174.00 FL	*174.00 FL
29	1		*REAR END PANEL	Dented	470.00 FL	*314.70 FL
30	1		*REAR END PANEL GARNISH	Twisted	160.00 FL	*85.00 FL
31	2		*REAR FENDER INNER TRIM	Deformed / Twisted	718.00 FL	*520.00 FL
32	1		*EXHAUST MUFFLER	Repair	1,099.00 FL	*- FL
33	2		*EXHAUST MUFFLER HANGER	Not Necessary	80.00 FL	*- FL
34	1		*TAILGATE INNER SEAL	Necessary	80.00 FS	*30.00 FS
35	1		*TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
36	1		*TAILGATE GLASS SOLAR FILM	Necessary	200.00 FS	*150.00 FS
37	1		*IROAD IN CAR CAMERA	Damaged	580.00 FS	*300.00 FS
38	10		*TAILGATE OUTER GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
39	10		*TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
40	4		*TAILLAMP CLIP	Not Necessary	20.00 FS	*- FS
41	1		*TAILGATE SEALANT	Necessary	80.00 FS	*50.00 FS
42	1		*REVERSE CAMERA	Serviceable	480.00 FS	*- FS
43	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
44	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
45	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
46	10		*REAR END PANEL GARNISH CLIP	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

1/6/23, 12:02 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	10		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
48	1		*REAR END PANEL BODY SEALANT	Necessary	80.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					12,636.00	7,217.10
- List Item Discount on L Items 20.00/20.00% (\$\$)					2,094.20	1,257.42
Total Parts (\$\$)					10,541.80	5,959.68
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO TRANSFER REAR WINDSCREEN GLASS	New	150.00	120.00
3	TO TRANSFER TAILGATE MECHANISM	New	150.00	60.00
4	TO FIT REVERSE SENSOR IN BUMPER }	New	50.00	50.00
5	INSTALL REVERSE SENSOR }	New	250.00	0.00
6	TO RUSTPROOF ON DAMAGED PARTS	New	150.00	60.00
7	TO REMOVE /REFIT EXHAUST MUFFLER TO FACILITATE REPAIRS	New	350.00	60.00
8	TO REMOVE INNER TRIM , GARNISH AND ETC TO FACILITATE REPAIR AND TO FIX BACK	New	280.00	80.00
9	TO REMOVE NECESSARY PARTS TO CUT OUT END PANEL ,REPAIR END PANEL REWELD END PANEL ,REPLACE ACCIDENT DAMAGE PARTS AND ALIGN THE SAME	New	1,200.00	800.00
10	TO PUTTY AND RESPRAY ACCIDENT DAMAGE AREAS	New	1,200.00	1,000.00
11	TO CONDUCT WATER TEST TO CHECK FOR LEAKAGE	New	50.00	0.00
Gross Labour Cost (S\$)			3,880.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >