



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNG 8349P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	876.00	876.00
1	FRONT BUMPER LH CHROME MOULDING	CRACKED	298.00	298.00
2	FRONT BUMPER SIDE RETAINER L/R @\$77.00	N/S DAMAGED	154.00	77.00
1	FRONT LH CONTROL UNIT	NOT NECESSARY	3,948.10	-
1	FRONT LH FENDER	TO REPAIR SEE LABOUR	425.00	-
1	FRONT LH FENDER INNER SHIELD	NOT NECESSARY	185.00	-
1	FRONT LH HEADLAMP	CUT	3,749.00	3,749.00
1	FRONT LH HEADLAMP LOWER BRACKET	CRACKED	68.00	68.00
1	FRONT NOSE PANEL	TORN	579.00	579.00
8	FRONT NOSE PANEL CLIPS @\$3.50	NECESSARY	28.00	20.00
1	FRONT NOSE PANEL LH BRACKET	NOT NECESSARY	58.00	-
10	FRONT NOSE PANEL RIVET @\$5.90	NECESSARY	59.00	20.00
1	FRONT NOSE PANEL RUBBER SEAL	NOT NECESSARY	38.00	-
	LESS 20% DISCOUNT		-2,093.02	-1,137.40
			8,372.08	4,549.60
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT LH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
			100.00	30.00
<b><u>LABOUR</u></b>				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)		80.00	30.00
	TO RESET SYSTEM AFTER REPAIR WORKS.	NOT NECESSARY	250.00	-
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		600.00	400.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT LH FENDER.		500.00	300.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		50.00	30.00
			1,480.00	760.00
<b>GRAND TOTAL</b>			<b>9,952.08</b>	<b>5,339.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>4,200.00</b>

Report Ref No. CS/AGI22012650/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**