

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012654/TVP3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00081732202		
Claimant Vehicle No :	GBJ2549U	Insured Vehicle No :	YL4554H		
Date of Loss:	06/12/2022	Nature of Claim:	TP	Claim No:	SNM22D209090/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2549U	Engine No:	1KD2833163
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR MT (M)	Chassis No:	JTFHT02P400246612
Reg. Date:	01/03/2019 (Man. Year: 2018)	Odometer:	133978 km
Colour:	Grey		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,786.67	4,337.17	2,449.50	36.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,870.00	1,330.00	41.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,986.67	6,207.17	3,779.50	37.85
Approved Total (Overridden) (S\$)		4,950.00		
(S\$)	9,986.67	4,950.00	5,036.67	50.43
+ GST 8.00/8.00% (S\$)	798.93	396.00	402.93	50.43
Nett Amount (S\$)	10,785.60	5,346.00	5,439.60	50.43

INSPECTION

Date of Assignment:	27/12/2022	
Date Inspected:	22/02/2023 Inspected At:	Efficient Motor & Engineering Works Pte Ltd (HQ) 37 Loyang Way Singapore 508734
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Apr 2023)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ2549U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	491.60 FL	*491.60 FL
2	2		*REAR BUMPER RETAINER LH/RH	Not Necessary	70.60 FL	*- FL
3	2		*REAR BUMPER UPPER COVER LH/RH	Not Necessary	202.40 FL	*- FL
4	2		*REAR BUMPER UPPER COVER RETAINER LH/RH	Not Necessary	69.00 FL	*- FL
5	1		*REAR END PANEL OUTER	Repair	371.40 FL	*- FL
6	1		*REAR WINDSCREEN GLASS	Broken	1,343.10 FL	*1,191.00 FL
7	1		*REAR WIPER MOTOR ASSY	Not Necessary	750.10 FL	*- FL
8	1		*TAILGATE	Bent	2,337.90 FL	*2,159.00 FL
9	1		*TAILGATE LOCK	Bent	299.60 FL	*299.60 FL
10	1		*TAILGATE WEATHERSTRIP	Cut	442.00 FL	*387.00 FL
11	1		*TAILGATE GARNISH	Cut	154.20 FL	*154.20 FL
12	1		*TAILGATE LOGO	Necessary	72.20 FL	*72.20 FL
13	1		*TAILGATE INNER TRIMBOARD	Cracked	488.30 FL	*488.30 FL
14	1		*REAR END STEP PLATE	Not Necessary	114.30 FL	*- FL
15	2		*TAIL LAMP LH/RH	Not Necessary	662.20 FL	*- FL
16	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
17	1		*REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
18	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
19	1		*70KM/H STICKER	Necessary	30.00 FS	*30.00 FS
20	1		*SEALANT	Necessary	80.00 FS	*60.00 FS
21	1		*REAR NO PLATE	Bent	45.00 FS	*45.00 FS
22	1		*PAN PACIFIC METAL PLATE	Necessary	80.00 FS	*40.00 FS
					Sub Total (\$\$)	8,753.90 5,647.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,967.23 1,310.73
					Total Parts (\$\$)	6,786.67 4,337.17

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD ,PANEL BEAT & ALIGN REAR PORTION ,TO REMOVE & REPLACE DAMAGED PARTS	New	1,200.00	700.00
2	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	100.00	30.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	30.00
5	TO PUTTY ,SPRAY PAINTING REAR PORTIONS & OTHER AFFECTED AREAS	New	1,000.00	700.00
6	TO TRANSFER TAILGATE COMPONENTS TO NEW TAILGATE	New	150.00	60.00
7	TO REMOVE & REFIT REAR WINDSCREEN GLASS	New	200.00	120.00
8	TO DO TAILGATE COMPANY STICKER	New	350.00	200.00
Gross Labour Cost (S\$)			3,200.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >