

ASS. REF: U.B. 1497 REF: CS/CT.127012654/TUP3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp. Ed Vehicle No: _____

at Work-shop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 866K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: G8J2549U Yr Regn: 2019, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiace C.C. 2982

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 133978 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT02P4 00246612

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/S / Rim / STD A/Rim or

Tyre Size: F: 195/15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Greenlander

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 22/2/23

Survey held at Efficient Motor

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

\$ + RS. \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / L.S. (\$ _____)

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY SINGAPORE 508734

VEHICLE NO : **GBJ2549U**

MAKE & MODEL : TOYOTA HI ACE VAN TURBO 5DR MT

CHASSIS NO : JTFHT02P400246612

DATE : 21 FEB 2023

CLAIM TYPE : TP CLAIM

D.O.A : 06 DEC 2022

TO : CHINA TAIPING

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER		\$ 491.60	\$ del 491.60
2	2	REAR BUMPER RETAINER LH/RH		\$ 35.30	\$ X 70.60
3	2	REAR BUMPER UPPER COVER LH/RH		\$ 101.20	\$ X 202.40
4	2	REAR BUMPER UPPER COVER RETAINER LH/RH		\$ 34.50	\$ X 69.00
5	1	REAR END PANEL OUTER		\$ 371.40	\$ Ry 371.40
6	1	REAR WINDSCREEN GLASS		\$ 1,343.10	\$ bro 1,343.10
7	1	REAR WIPER MOTOR ASSY		\$ 750.10	\$ X 750.10
8	1	TAILGATE		\$ 2,337.90	\$ bt 2,337.90
9	1	TAILGATE LOCK		\$ 299.60	\$ bt 299.60
10	1	TAILGATE WEATHERSTRIP		\$ 442.00	\$ ant 442.00
11	1	TAILGATE GARNISH		\$ 154.20	\$ ant 154.20
12	1	TAILGATE LOGO		\$ 72.20	\$ nor 72.20
13	1	TAILGATE INNER TRIMBOARD		\$ 488.30	\$ cur 488.30
14	1	REAR END STEP PLATE		\$ 114.30	\$ X 114.30
15	2	TAIL LAMP LH/RH		\$ 331.10	\$ LH?, RH X 662.20
				\$ 7,366.80	\$ 7,868.90

P - \$5628.9 LESS 25% = \$4221.67

TOTAL PRICE	\$ 7,868.90
LESS 25%	\$ 1,967.23
SUB TOTAL PRICE	\$ 5,901.68

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIP SET		\$ 50.00	\$ 30 net 50.00
2	1	REVERSE SENSOR		\$ 250.00	\$ 200 net 250.00
3	1	REVERSE CAMERA		\$ 350.00	\$ X 350.00
4	1	70KM/H STICKER		\$ 30.00	\$ net 30.00
5	1	SEALANT		\$ 80.00	\$ 60 net 80.00
6	1	REAR NO. PLATE		\$ 45.00	\$ bf 45.00
7	1	PAN PACIFIC METAL PLATE		\$ 80.00	\$ net 40 80.00

S/N = \$405

TOTAL S/NETT	\$ 885.00	\$ 885.00
--------------	-----------	-----------

Labour Charges

1	To cut/weld, panel beat & align Rear portion, to remove & replace damaged parts.	\$ 1,200.00	700
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 100.00	30
4	To remove & replace reverse sensor.	\$ 100.00	30
5	To putty, spray painting Rear Portions & other affected areas.	\$ 1,000.00	700
6	To transfer tailgate components to new tailgate.	\$ 150.00	60
7	To remove & refit rear windscreen glass.	\$ 200.00	120
8	To do TAILGATE company sticker.	\$ 350.00	200

Tanfer 97995749

WPS 22/2/23 & 280 pm

1/2 Memy after repair
Tanfer C/Handbook
Gdang

TOTAL LABOUR L = \$1870	\$ 3,200.00
-------------------------	-------------

Total Cost of Repairs	\$ 9,986.68
-----------------------	-------------

(Total parts + Total S/Nett + Total Labour Cost)

TOTAL - \$6496.67 LESS 20% = \$5197.33

FINAL - COR L/S \$5,200.00 IN 6 DAYS