

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012656/ANP3Q2**Date:** 05/04/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00178402203

Claimant Vehicle No : SMU9502U **Insured Vehicle No :** SJB8393J

Date of Loss: 16/12/2022 Nature of Claim: TP Claim No: SNM22D209102/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU9502U**

Make & Model: MERCEDES-BENZ GLB200, 1.3 PREMIUM PLUS AMG LINE 7-SEATER (A) Engine No: 28291480311566

Reg. Date: 09/09/2020 (Man. Year: 2020) Chassis No: W1N2476872W033490

Colour: Red Odometer: 57083 km

Engine Capacity: 1332 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/45 R20 Rear Tyre Size: 255/45 R20

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,756.07	12,609.27	10,146.80	44.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,490.00	1,270.00	33.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,516.07	15,099.27	11,416.80	43.06
Approved Total (Overridden) (S\$)		12,000.00		
(S\$)	26,516.07	12,000.00	14,516.07	54.74
+ GST 8.00/8.00% (S\$)	2,121.29	960.00	1,161.29	54.74
Nett Amount (S\$)	28,637.36	12,960.00	15,677.36	54.74

INSPECTION

Date of Assignment: 19/12/2022

Date Inspected: 20/12/2022 Inspected At: 2 KAKI BUKIT AVE 2
#01-17 KAKI BUKIT AUTOHUB
SINGAPORE 417921
Repairer: N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Apr 2023)

Parts: M1-SUV MERCEDES-BENZ GLB200 1.3 PREMIUM PLUS AMG LINE 7-SEATER (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU9502U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Dented	2,105.00 FL	*2,105.00 FL
2	1		*FRONT RH DOOR PROTECTOR GARNISH	Cut	289.00 FL	*289.00 FL
3	1		*FRONT RH DOOR WEATHER STRIP	Necessary	269.00 FL	*269.00 FL
4	1		*FRONT RH DOOR WINDSCREEN GLASS	Cut	482.00 FL	*482.00 FL
5	1		*FRONT RH FENDER (ALUMINIUM)	Dented	869.00 FL	*869.00 FL
6	1		*FRONT RH FENDER ARCH GARNISH	Cut	325.00 FL	*325.00 FL
7	1		*FRONT RH FENDER INNER SHIELD (FRONT)	Not Necessary	168.00 FL	*- FL
8	1		*FRONT RH FENDER INNER SHIELD (REAR)	Not Necessary	168.00 FL	*- FL
9	1		*FRONT RH KNUCKLE ARM	Damaged	779.00 FL	*779.00 FL
10	1		*FRONT RH KNUCKLE ARM BEARING	Damaged	569.00 FL	*569.00 FL
11	1		*FRONT RH LOWER ARM	Bent	659.00 FL	*659.00 FL
12	1		*FRONT RH SHOCK ABSORBER	Not Necessary	569.00 FL	*- FL
13	1		*FRONT RH TIE ROD END	Not Necessary	268.00 FL	*- FL
14	1		*REAR BUMPER	Torn	1,789.00 FL	*1,353.00 FL
15	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	91.00 FL	*- FL
16	1		*REAR RH CONTROL ARM	Not Necessary	325.00 FL	*- FL
17	1		*REAR RH DOOR ARCH GARNISH	Cut	168.00 FL	*168.00 FL
18	1		*REAR RH DOOR PROTECTOR GARNISH	Not Necessary	276.00 FL	*- FL
19	1		*REAR RH FENDER ARCH GARNISH	Cut	315.00 FL	*315.00 FL
20	1		*REAR RH KNUCKLE ARM	Damaged	782.30 FL	*782.30 FL
21	1		*REAR RH KNUCKLE ARM BEARING	Damaged	523.00 FL	*523.00 FL
22	1		*REAR RH LOWER ARM	Bent	523.00 FL	*523.00 FL
23	1		*REAR RH SHOCK ABSORBER	Not Necessary	435.00 FL	*- FL
24	1		*REAR RH UPPER ARM	Not Necessary	316.00 FL	*- FL
25	1		*FRONT RH 255/45ZR20 TYRE (RUN FLAT)	Not Necessary	950.00 FS	*- FS
26	1		*SET FRONT RH DOOR PROTECTOR GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
27	1		*FRONT RH DOOR STICKER	Necessary	1,100.00 FS	*300.00 FS
28	1		*SET FRONT RH FENDER ARCH GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
29	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
30	1		*FRONT RH FENDER STICKER	Necessary	800.00 FS	*300.00 FS
31	1		*FRONT RH SPORT RIM	Cut	1,600.00 FS	*1,000.00 FS
32	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
33	1		*REAR BUMPER STICKER	Necessary	1,100.00 FS	*300.00 FS
34	1		*REAR RH 225/45ZR20 TYRE (RUN FLAT)	Not Necessary	950.00 FS	*- FS
35	1		*SET REAR RH DOOR PROTECTOR GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*REAR RH DOOR STICKER	Necessary	1,100.00 FS	*300.00 FS
37	1		*SET REAR RH FENDER ARCH GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
38	1		*REAR RH FENDER STICKER	Necessary	1,500.00 FS	*300.00 FS
39	1		*REAR RH SPORT RIM	Cut	1,600.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	24,062.30	13,610.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,306.23	1,001.03
Total Parts (\$\$)	22,756.07	12,609.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	400.00	150.00
2	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING ,AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE ,CHARGE FRONT SUSPENSION PARTS ,ABSORBER ,LOWER ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB, DRIVE SHAFT ,ANTI-ROLL BAR ,TOP-ARM AND STEERING RACK AND PINION	New	350.00	220.00
4	TO REMOVE ,CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ,ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM ,KNUCKLE ARM ,WHEEL BEARING ,BEARING HUB AND ETC	New	350.00	220.00
5	TO ROAD TEST DRIVING CHECK AND RESETTNG WHEEL ALIGNMENT SYSTEM	New	100.00	80.00
6	TO TRANSFER DOOR GLASS ,REGULATOR GEAR ,MOTOR ,RAILING ,CHANNEL ,TRIM BOARD ,MECHANISM LOCK AND HANDLE	New	80.00	80.00
7	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	1,000.00
8	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	60.00
Gross Labour Cost (S\$)			3,760.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >