4/19/23, 12:31 PM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIS22012657/AYA3Q2

19/04/2023 Date:

**REFERENCE** 

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2002451400

**Claimant Vehicle** SMK7535R Insured Vehicle No: **SMA388Y** 

No:

Date of Loss: 10/12/2022 Nature of Claim: TP Claim No: 202222008809

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SMK7535R** 

Make & Model: K24Z98503488 HONDA CR-V, 2.4 (A) Engine No:

Reg. Date: 02/11/2015 (Man. Year: 2015) Chassis No: MRHRM3850GP000137

Colour: Odometer: 123781 km Grey

**Engine Capacity:** 2354 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 225/55 R18 225/55 R18 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                    | Repairer's           | Adjuster's | Difference | Diff % |
|-----------------------------------|----------------------|------------|------------|--------|
| Parts                             | 3,681.60             | 1,062.88   | 2,618.72   | 71.13  |
| Miscellaneous Items               | 0.00                 | 0.00       | 0.00       |        |
| Labour                            | 2,800.00             | 930.00     | 1,870.00   | 66.79  |
| Paintwork Labour                  | 0.00                 | 0.00       | 0.00       |        |
| Towing                            | 0.00                 | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$)      | 6,481.60             | 1,992.88   | 4,488.72   | 69.25  |
| Approved Total (Overridden) (S\$) |                      | 1,600.00   |            |        |
| Nett Amount (S\$)                 | 6,481.60             | 1,600.00   | 4,881.60   | 75.31  |
| + Car Rental (6.0 x S             | \$100.00/day) (S\$)  | 600.00     |            |        |
| + Doo                             | c/Search Fee (S\$)   | 7.45       |            |        |
|                                   | Nett Liability (S\$) | 2,207.45   |            |        |
| Global Sur                        | n Settlement (S\$)   | 2,200.00   |            |        |

**INSPECTION** 

Date of Assignment: 13/12/2022

Zero Gravity (Kaki Bukit) Date Inspected:

2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub 15/12/2022 Inspected At:

Singapore 417921

Estimated Period of Repair: 4.0 days

ADRIAN LING Adjuster: Manager: Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2023)

Parts: M1-SUV HONDA CR-V 2.4 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK7535R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

| No.   | Qty    | Part No.     | Particulars                      | Condition                     | Repairer's  | Amount     |
|-------|--------|--------------|----------------------------------|-------------------------------|-------------|------------|
| 1     | 1      |              | *REAR END PANEL                  | Not Necessary                 | 517.10 FL   | *- FL      |
| 2     | 1      |              | *LAMP (R/H/R)                    | Not Necessary                 | 354.40 FL   | *- FL      |
| 3     | 1      |              | *FENDER (R/H/R)                  | Not Necessary                 | 1,006.20 FL | *- FL      |
| 4     | 1      |              | *REAR BUMPER                     | Deformed                      | 530.10 FL   | *530.10 FL |
| 5     | 6      |              | *BUMPER CLIP                     | Necessary                     | 30.00 FL    | *30.00 FL  |
| 6     | 1      |              | *BUMPER SIDE RETAINER (R/H/R)    | Damaged                       | 20.90 FL    | *20.90 FL  |
| 7     | 1      |              | *BUMPER SIDE (LOWER) (R/H/R)     | Deformed                      | 127.70 FL   | *127.70 FL |
| 8     | 1      |              | *PROTECTOR (FENDER) ARCH (R/H/R) | Deformed                      | 140.30 FL   | *140.30 FL |
| 9     | 1      |              | *REAR BUMPER REFLECTOR (R/H)     | Cracked                       | 92.60 FL    | *92.60 FL  |
| 10    | 1      |              | *REAR BUMPER LIP                 | Deformed                      | 313.20 FL   | *313.20 FL |
| 11    | 1      |              | *MUD FLAG (R/H/R)                | Cut                           | 73.80 FL    | *73.80 FL  |
| 12    | 1      |              | *KNUCKLE (REAR) (R/H)            | Not Necessary                 | 463.80 FL   | *- FL      |
| 13    | 1      |              | *WHEEL BEARING (R/H/R)           | Not Necessary                 | 394.40 FL   | *- FL      |
| 14    | 1      |              | *SET REVERSE SENSOR              | Not Necessary                 | 380.00 FS   | *- FS      |
| 15    | 1      |              | *BTL REAR END PANEL SEALANT      | Not Necessary                 | 50.00 FS    | *- FS      |
| F=Fra | nchise | part. S=SpcN | ett. L=ListItemDisc.             | _                             |             |            |
|       |        |              |                                  | Sub Total (S\$)               | 4,494.50    | 1,328.60   |
|       |        |              | - List Item Discount o           | on L Items 20.00/20.00% (S\$) | 812.90      | 265.72     |
|       |        |              |                                  | Total Parts (S\$)             | 3,681.60    | 1,062.88   |
|       |        |              | Report was unsubmitted o         | during this print-out.        |             |            |

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

| No         | Particulars   | Lab.Type     | Repairer's | Amount |
|------------|---|--------------|------------|--------|
| <u>Lab</u> | our Items   |              |            |        |
| 1          | PANEL BEAT & REPAIR REAR DAMAGE                       | New          | 1,000.00   | 400.00 |
| 2          | TO PUTTY AND RE-SPRAY AFFECTED PORTION                | New          | 900.00     | 400.00 |
| 3          | TO REMOVE AND REFIT COMPONENTS/ FACILITATE THE REPAIR | New          | 120.00     | 0.00   |
| 4          | TO CHECK WIRING SYSTEM FOCUS LIGHTINGS                | New          | 50.00      | 30.00  |
| 5          | TO REMOVE REVERSE SENSOR                              | New          | 80.00      | 50.00  |
| 6          | TO PROVIDE UNDER TURFCOAT                             | New          | 150.00     | 50.00  |
| 7          | TO COMPUTERISE ADJUST WHEEL ALIGNMENT                 | New          | 150.00     | 0.00   |
| 8          | TO CHECK UNDERCARRIAGE AND REPLACE DAMAGED PARTS      | New          | 350.00     | 0.00   |
|            | Gross Labour Cost (S\$)                               |              | 2,800.00   | 930.00 |
|            | Report was unsubmitted during thi                     | s print-out. |            |        |

< END OF ESTIMATES >