

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22012663/UYA3Q2**Date:** 14/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210009833
Claimant Vehicle No :	SJQ4522B	Insured Vehicle No :	SMX7374U
Date of Loss:	18/12/2022	Nature of Claim:	TP
		Claim No:	4114184697SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ4522B	Engine No:	1NZD271880
Make & Model:	TOYOTA PREMIO, 1.5 F (A)	Chassis No:	NZT2603036584
Reg. Date:	12/05/2009 (Man. Year: 2008)	Odometer:	308767 km
Colour:	Maroon		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,528.40	6,312.72	12,215.68	65.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,290.00	2,090.00	1,200.00	36.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,818.40	8,402.72	13,415.68	61.49
Approved Total (Overridden) (S\$)		6,700.00		
(S\$)	21,818.40	6,700.00	15,118.40	69.29
+ GST 7.00/7.00% (S\$)	1,527.29	469.00	1,058.29	69.29
Nett Amount (S\$)	23,345.69	7,169.00	16,176.69	69.29
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,471.00		

INSPECTION

Date of Assignment:	19/12/2022	
Date Inspected:	19/12/2022	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut / Torn	1,681.10 F	*1,150.20 FL
2	1		*FRONT BUMPER SIDE RETAINER O/S	Bent	90.00 F	*90.00 FL
3	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	108.00 F	*- FL
4	1		*FRONT BUMPER BEAM	Not Necessary	561.10 F	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	140.10 F	*- FL
6	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	1		*HEADLAMP O/S	Not Necessary	1,980.00 F	*- FL
8	1		*FRONT BRACE PANEL	Not Necessary	121.00 F	*- FL
9	1		*FRONT FENDER O/S	Badly Dented	1,522.00 F	*891.20 FL
10	1		*FRONT FENDER INNER SHIELD O/S	Torn	322.00 F	*299.50 FL
11	1		*FRONT FENDER INNER VERTICAL GARNISH O/S	Twisted	118.10 F	*118.10 FL
12	1		*SET FRONT FENDER INNER SHIELD CLIPS O/S	Necessary	50.00 F	*50.00 FL
13	1		*FRONT SUPPORT PANEL	Not Necessary	1,160.00 F	*- FL
14	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	210.00 F	*- FL
15	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	50.00 F	*- FL
16	1		*WIPER WASHER TANK	Not Necessary	182.00 F	*- FL
17	1		*ROCKER PANEL GARNISH O/S	Repair	991.00 F	*- FL
18	1		*SET ROCKER PANEL GARNISH CLIPS O/S	Not Necessary	50.00 F	*- FL
19	1		*FRONT SHOCK ABSORBER O/S	Bent	485.10 F	*485.10 FL
20	1		*FRONT LOWER ARM O/S	Bent	671.80 F	*671.80 FL
21	1		*FRONT KNUCKLE ARM O/S	Bent	545.80 F	*545.80 FL
22	1		*FRONT KNUCKLE ARM BEARING O/S	Damaged	355.10 F	*285.50 FL
23	1		*FRONT DRIVE SHAFT O/S	Not Necessary	1,488.20 F	*- FL
24	1		*SET FRONT SPORT RIM	Warped	1,250.00 FS	*500.00 FS
25	1		*FRONT DOOR O/S	Badly Dented	1,650.10 F	*1,650.10 FL
26	1		*FRONT DOOR OUTER PROTECTOR O/S	Bent	288.90 F	*288.90 FL
27	1		*FRONT DOOR HINGE LOWER O/S	Bent	105.00 F	*105.00 FL
28	1		*FRONT DOOR CHECKER O/S	Not Necessary	166.00 F	*- FL
29	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	80.00 F	*80.00 FL
30	1		*FRONT DOOR INNER RUBBER O/S	Not Necessary	211.80 F	*- FL
31	1		*FRONT DOOR INNER TRIM BOARD O/S	Not Necessary	855.10 F	*- FL
32	1		*FRONT DOOR OUTER PILLAR O/S	Dented / Bent	989.10 F	*989.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,528.40	8,250.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,937.58
Total Parts (\$\$)	18,528.40	6,312.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO RESET & REPROGRAMME SYSTEM	New	100.00	0.00
3	TO DISMANTLE & REFIX FRONT UNDER CARRIAGE	New	360.00	150.00
4	TO CONDUCT WHEEL ALIGNMENT	New	100.00	80.00
5	TO REFILL AIR CON GAS	New	100.00	0.00
6	TO TRANSFER FRONT DOOR MECHANISM	New	80.00	60.00
7	TO SPRAY RUST PROOFING	New	200.00	80.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,100.00	700.00
9	TO PUTTY & SPRAY PAINTING	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			3,290.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >