

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI22012675/SWY3Q2**Date:** 23/03/2023**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000213
<b>Claimant Vehicle No :</b>	SHC1723E	<b>Insured Vehicle No :</b>	SLK5328Y
Date of Loss:	14/12/2022	Nature of Claim:	TP
		Claim No:	M2207224

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHC1723E</b>	Engine No:	G4LEKU211732
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Chassis No:	KMHC851CVKU146332
Reg. Date:	14/05/2019 (Man. Year: 2019)	Odometer:	521615 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,761.80	962.32	799.48	45.38
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,060.00	630.00	430.00	40.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,832.80</b>	<b>1,603.32</b>	<b>1,229.48</b>	<b>43.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
<b>(S\$)</b>	2,832.80	1,300.00	1,532.80	54.11
<b>+ GST 7.00/8.00% (S\$)</b>	198.30	104.00	94.30	47.55
<b>Nett Amount (S\$)</b>	<b>3,031.10</b>	<b>1,404.00</b>	<b>1,627.10</b>	<b>53.68</b>

**INSPECTION**

Date of Assignment:	20/12/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/12/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

**Adjuster:** S Mohamed Irfan Bin Mohamed Iqbal**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 22 Mar 2023)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1723E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	459.40 FL	*459.40 FL
2	1		*REAR BUMPER CENTRE MOULDING	Broken	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
4	2		*REAR BUMPER REINFORCEMENT STAY LH/RH	Not Necessary	276.20 FL	*- FL
5	2		*REAR BUMPER BRACKET LH /RH	Not Necessary	111.60 FL	*- FL
6	1		*REAR BUMPER NUMBER PLATE W/HOLDER	Cracked	55.00 FL	*55.00 FS
7	1		*REAR REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
8	10		*REAR BUMPER CLIPS	Necessary	22.00 FS	*22.00 FL
9	1		*REAR FOG LAMP	Cracked	201.50 FL	*201.50 FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					2,151.75	1,189.15
- List Item Discount on L Items 20.00/20.00% (\$\$)					389.95	226.83
Total Parts (\$\$)					1,761.80	962.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
Gross Labour Cost (\$\$)			1,060.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >