

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22012680/AVY3M4**Date:** 17/02/2023**REFERENCE**

Insured/Claimant: SIMON LEE CHOONG CHAN Policy No: MPC22P00219000
Date of Loss: 16/12/2022 Nature of Claim: OD Claim No: DMPC2200638H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME2270T**
Make & Model: TOYOTA HARRIER, 2.0 M GRADE (A) Engine No: 8ARZ136418
Reg. Date: 24/09/2018 (Man. Year: 2018) Chassis No: JTEZB3GH30J002930
Colour: Red Odometer: 104026 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$118,000.00
Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18
Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm
Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,922.00	1,622.50	3,299.50	67.04
Miscellaneous Items	900.00	550.00	350.00	38.89
Labour	3,120.00	1,110.00	2,010.00	64.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,942.00	3,282.50	5,659.50	63.29
Approved Total (Overridden) (\$\$)		2,600.00		
(\$\$)	8,942.00	2,600.00	6,342.00	70.92
+ GST 7.00/7.00% (\$\$)	625.95	182.00	443.95	70.92
Nett Amount (\$\$)	9,567.95	2,782.00	6,785.95	70.92

INSPECTION

Date of Assignment: 19/12/2022 Present Location: Jack Cars Enterprise Pte Ltd (HQ)
BLK 3007 UBI ROAD 1 #01-450
Date Inspected: 20/12/2022 Inspected At: SINGAPORE 408700
REPAIRER: JACK CARS ENTERPRISE PTE LTD
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Feb 2023)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME2270T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT REAR DOOR (WCP)	Dented	1,450.00 F	*750.00 F
2	1		*REAR BUMPER (WCP)	Repair	900.00 F	*- F
3	1		*REAR LOWER LIPS (WCP)	Deformed	420.00 F	*250.00 F
4	1		*REAR LEFT FENDER (WCP)	Repair	780.00 F	*- F
Supplementary #1						
5	1		*DOOR GARNISH - LEFT (WCP)	Cracked	310.00 F	*125.00 F
6	1		*SIDE SKIRT - LEFT (WCP)	Cut	420.00 F	*350.00 F
F=Franchise part.						
Sub Total (\$\$)					4,280.00	1,475.00
+ Margin on L,N Items 15.00/10.00% (\$\$)					642.00	147.50
Total Parts (\$\$)					4,922.00	1,622.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	CLIPS , RIVET & SCREWS Not Necessary	100.00	0.00
Supplementary #1				
2	1	RIM - REAR LEFT Cut	550.00	550.00
3	1	TYRE - REAR LEFT Not Necessary	250.00	0.00
Sub Total (S\$)			900.00	550.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	New	1,000.00	400.00
2	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00	600.00
3	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	220.00	60.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	200.00	0.00
5	TO REMOVE & REINSTALL SENSORS	New	200.00	50.00
Gross Labour Cost (S\$)			3,120.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >