2/27/23, 2:36 PM Merimen e-Claims

> Adjuster Letter/DV not verified. This claim is to be authorized on the insurer's behalf. Submissions will not be allowed until the Letter of Offer/DV is VERIFIED. Click on 'View Letter/DV' to verify the offer.

> > You cannot authorize this offer because Adjuster Letter/DV not verified. File to be authorized by your superior.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited **Our File No:** CS/ICS22012680/AVY3M4 10 Eunos Road 8, #09-04A Singapore Post Centre

Date: 27/02/2023 Singapore 408600

REFERENCE

Insured/Claimant: SIMON LEE CHOONG CHAN Policy No: MPC22P00219000

Date of Loss: 16/12/2022 Nature of Claim: OD Claim No: DMPC2200638H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

SME2270T Reg No:

Make & Model: TOYOTA HARRIER, 2.0 M GRADE (A) Engine No: 8ARZ136418 Reg. Date: 24/09/2018 (Man. Year: 2018) Chassis No: JTEZB3GH30J002930

Odometer: 104026 km Colour: Red

Engine Capacity: 1998 cc Market Value/New Car Price: S\$118,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Engine Modification: Nο Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18 Front Left Side: Rear Left Side: Tourador 6 mm Tourador 6 mm Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,922.00	1,622.50	3,299.50	67.04
Miscellaneous Items	900.00	550.00	350.00	38.89
Labour	3,120.00	1,110.00	2,010.00	64.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,942.00	3,282.50	5,659.50	63.29
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	8,942.00	2,600.00	6,342.00	70.92
+ GST 7.00/7.00% (S\$)	625.95	182.00	443.95	70.92
Nett Amount (S\$)	9,567.95	2,782.00	6,785.95	70.92

INSPECTION

Date of Assignment: Present Location: 19/12/2022 Jack Cars Enterprise Pte Ltd (HQ)

BLK 3007 UBI ROAD 1 #01-450 SINGPORE 408700

Inspected At: Date Inspected: 20/12/2022 REPAIRER: JACK CARS ENTERPRISE PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2023)

TOYOTA HARRIER 2.0 M GRADE (A) (Catalogue:Merimen Singapore 1.0) Parts: M1-SUV

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SME2270T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF

ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Amount	Repairer's	Condition	Particulars	Qty Part No.	No.
*750.00 F	1,450.00 F	Dented	*LEFT REAR DOOR (WCP)	1	1
*- F	900.00 F	Repair	*REAR BUMPER (WCP)	1	2
*250.00 F	420.00 F	Deformed	*REAR LOWER LIPS (WCP)	1	3
*- F	780.00 F	Repair	*REAR LEFT FENDER (WCP)	1	4
				lementary #1	Supp
*125.00 F	310.00 F	Cracked	*DOOR GARNISH - LEFT (WCP)	1	5
*350.00 F	420.00 F	Cut	*SIDE SKIRT - LEFT (WCP)	1	6
				nchise part.	F=Fra
1,475.00	4,280.00	Sub Total (S\$)			
147.50	642.00	in on L,N Items 15.00/10.00% (S\$)	+		
1,622.50	4,922.00	Total Parts (S\$)			

Recommended Miscellaneous Items

No	Qt	y Particulars		Repairer's	Amount		
Mis	Miscellaneous Items						
1	1	CLIPS , RIVET & SCREWS Not Necessary		100.00	0.00		
<u>Su</u>	<u>pple</u>	mentary #1					
2	1	RIM - REAR LEFT Cut		550.00	550.00		
3	3 1	TYRE - REAR LEFT Not Necessary		250.00	0.00		
			Sub Total (S\$)	900.00	550.00		

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEM KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	IENTS; New	1,000.00	400.00
2	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	1,500.00	600.00
3	TO REMOVE AND REINSTALL TAILGATE COMPONENTS	New	220.00	60.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	200.00	0.00
5	TO REMOVE & REINSTALL SENSORS	New	200.00	50.00
	G	ross Labour Cost (S\$)	3,120.00	1,110.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >