



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 8071X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR BODY PANEL ASSY	TO REPAIR SEE LABOUR	1,678.69	-
1	REAR BUMPER	BENT	1,088.78	1,088.78
1	REAR COMPARTMENT COVER	TO REPAIR SEE LABOUR	1,157.89	-
1	REAR COMPARTMENT COVER LOCK	BENT	125.68	125.68
1	REAR LAMP R/H	CRACKED	250.25	250.25
1	REAR SIGNAL LIGHT L/H	DISTORTED	90.89	90.89
	LESS 10% DISCOUNT		-439.22	-155.56
			3,952.96	1,400.04
<b>SPECIAL NETT ITEMS</b>				
1	REAR ENGINE HOOD 60KMH STICKER (SN)	NECESSARY	20.00	20.00
1	REAR ENGINE HOOD AWC STICKER(SN)	NECESSARY	20.00	20.00
			40.00	40.00
<b>LABOUR</b>				
	TO CUT ,WELD OFF REAR BODY PANEL ASSY AND RENEW THE SAME AND RENEWAL OF THE NECESSARY PARTS ,FINAL CHECKING AND TESTING.INCLUSIVE OF THE REPAIR OF REAR BODY PANEL ASSY AND REAR COMPARTMENT COVER .		2,500.00	1,500.00
	SPRAY PAINTING OF THE AFFECTED PORTION.		2,000.00	1,000.00
			4,500.00	2,500.00
<b>GRAND TOTAL</b>			<b>8,492.96</b>	<b>3,940.04</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,150.00</b>

Report Ref No. CS/FCI22012684/Tqy3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.