

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 4281A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	1,020.00	1,020.00
1	FRONT BUMPER RETAINER LH	SCRATCHED	89.00	38.70
1	FRONT HEADLAMP LH	NOT NECESSARY	825.00	-
1	FRONT FENDER LH	BENT	495.00	393.00
1	FRONT FOGLAMP LH	NOT NECESSARY	130.50	-
1	FRONT FOGLAMP COVER LH	NOT NECESSARY	48.60	-
1	FRONT FENDER UNDER-DUST COVER LH (SHIELD)	CRACKED	139.50	139.50
1	FRONT GRILLE ASSY	CRACKED	304.50	304.50
1	FRONT BUMPER UNDER-DUST COVER	CRACKED	145.00	145.00
1	FRONT GRILLE INNER BRACKET LH	NOT NECESSARY	420.00	-
	LESS 20% DISCOUNT		-723.42	-408.14
			2,893.68	1,632.56
	SPECIAL NETT ITEMS			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	FRONT FENDER UNDER-DUST COVER CLIPS (SN)	NECESSARY	40.00	30.00
			80.00	60.00
	<u>LABOUR</u>			
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		1,000.00	500.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER).		800.00	400.00
	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTING & RESET HEADLAMP FOCUSING.		180.00	30.00
	COMPUTERIZED ALIGNMENT.		120.00	60.00
			2,100.00	990.00
	GRAND TOTAL		5,073.68	2,682.56

Report Ref No. CS/SMR22012686/Rny3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,150.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR22012686/Rny3e2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**