	AIG 220 12687 (Upg)
From: Date:	Veh No: \$1 N 263R Yr Regn: 23/01/0
Estimated Cost:	Type: M.Oar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or A/ 1.8
To Inspect Vehicle No: SJN 2631	Make: Toysto corollo AHES c.c 1794
at Workshop m/s	Colour A/C: Insured / Std / NI //NA
of	Sp.Reading DR 447 T/Radio: Insured / Std / NI / NA
Insured: SKSISOLI	Eng/No:
Policy No.	C/No: MROS3 ZEE 206 11245
Claims No.	Gen. Cond Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt-or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil (S/Pim / STD A/Rim or
IVIANO OI VOII.	Tyre Size: F: 228/45-2117
(Policy Condition)	R:
Remark: The veh had commenced its N/S	D/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front 6 Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm
Est. Repairs: 4 days Res.: Yes or No	D.O.A. 18/12/22 D.O.I. 20/12/22
Lum Sum: 22 % 3 Val.: Yes or No	Survey held at
a va	
CA / REV / REP. / 24 HRS	01/0
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction Que / UK.	
me used 22-01-2024	17A & 3 411
Date / Time Action / Instruction Dez 10k. Coe une 22-01-2024 (1/23 4/5 \$ 1900 informed	Elia
(40) /3 # 1700	
	,
the second secon	
	<u> </u>
Data/Time File Base to?	Dave Of Panair
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:)S+RS,SI
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee: Transportation:

TOTAL

SJN 263 R

REG NO. :

MAKE/MODEL:

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08<mark>-1339 Singapore 470130</mark>

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

• To display damaged part(s) during resurvey

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

16 January 2023

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

TOYOTA COROLLA ALTIS

QTY	DESCRIPTION				AMT(S\$)
	LIST ITEMS				Chini (194)
1	Rear windscreen moulding	11		\$	89.50 X
1	Rear taillamp -RH	SER		\$ 383.10	410.95
1	Rear bumper	De/Toin		\$ 188.10	680.60
1	Rear bumper reflector	11		\$	75.50 X
1	Rear bumper side retainer of	s cou		\$	65.50
1	Rear fender -RH	R		\$	1,081.60 X
1	Rear fender inner shield	11		\$	55.60 ¥
1	Rear wheel hub with bearing	11		\$	613.60 X
1	Rear shock absorber	11		\$	169.10 🗸
1	Rear axle	^^		\$	2,257.70 🗙
				\$	5,499.65
			Less 25%	\$	1,374.91
				\$	4,124.74

	SPECIAL NEIT ITEMS	11	
1	Rear windscreen sealant		\$ 80.00 💉
1	Rear bumper clip (1 set)	111	\$ 50.00
1	Rear reverse sensor (1 se	t) 11	\$ 350.00 🗴
1	Rear fender inner shield o	lip (1 set) 🔥 🐧	\$ 25.00 人
1	Rear tyre	su	\$ 400.00 X
1	Rear sport rim -RH	cui	\$ C 52 00.008
			\$ 1,705.00

S/N	LABOUR CHARGES	
1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 180.00 60
3	To remove and refit rear reverse sensor.	\$ 150.00 (2)
4	To remove and refit rear windscreen glass.	\$ 11 180.00 X
5	To apply undercoating.	\$ 180.00 X
6	Panel beating.	\$ 1,600.00 \$20
7	To re-spray painting on the affected areas.	\$ 1,500.00 400
		\$ 3,870.00

GRAND TOTAL:

9,699.74