



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 7125J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT HEADLAMP COVER COMPLETE (NPA) (CONSISTENT)	SERVICEABLE	-	-
1	FRONT WHEEL FENDER SIDE STAND(CONSISTENT)	CUT	90.00	90.00
1	RHS FRONT FAIRING (CONSISTENT)	CUT	180.00	180.00
1	LHS FRONT FAIRING (CONSISTENT)	CUT	180.00	180.00
2	RHS & LHS SIGNAL LAMP (NPA)(CONSISTENT)	SERVICEABLE	-	-
1	RHS BOARD FOOT REST SIDE PROTECTOR (CONSISTENT)	CUT	98.00	98.00
1	RHS REAR SEAT FAIRING (CONSISTENT)	CUT	150.00	150.00
1	HANDLE BAR (CONSISTENT)	SERVICEABLE	350.00	-
1	SET HANDLE BAR GRIPS RH & LH(CONSISTENT)	NOT NECESSARY	48.00	-
1	SET HANDLE BAR BALANCER RH & LH (O/S) (CONSISTENT)	CUT	75.00	38.00
1	BRAKEL LEVER (CONSISTENT)	CUT	90.00	75.00
1	CLUTCH LEVER (CONSISTENT)	CUT	90.00	75.00
1	LHS SIDE MIRROR (CONSISTENT)	BROKEN	50.00	50.00
2	FRONT SIGNAL LAMPS RH & LH (NPA) (CONSISTENT)	SERVICEABLE	-	-
2	FRO SIGNAL LAMP COVER COMPLETE (BLACK) (CONSISTENT)	GRAZED	175.00	175.00
1	FRONT FAIRING (CONSISTENT)	CUT	700.00	485.00
1	SIDE STAND (CONSISTENT)	CUT	75.00	75.00
1	MAIN STAND (CONSISTENT)	CUT	120.00	120.00
1	EXHAUST SILENCER (CONSISTENT)	DENTED / BENT	250.00	250.00
1	EXHAUST SILENCER PROTECTOR (CONSISTENT)	DISTORTED	78.00	78.00
	LESS 10% DISCOUNT		-279.90	-211.90
			2,519.10	1,907.10
<u>SPECIAL NETT ITEMS</u>				
1	IU UNIT WITH HOLDER (SN) (CONSISTENT)	NOT NECESSARY	150.00	-
1	SET BOLTS /MISC/SEALS (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR BOX (SN) (CONSISTENT)	CUT	250.00	250.00
1	REAR BOX SUPPORT BRACKET (SN) (CONSISTENT)	BENT	90.00	90.00
			520.00	340.00

Report Ref No. CC4/ASM22012688/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REPLACE DAMAGED PARTS AND COMPONENTS .		450.00	300.00
	TO REMOVE ,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS .	NOT NECESSARY	60.00	-
	TO SPRAY PAINT RHS FRONT FAIRING AND RHS REAR FAIRING.	NOT NECESSARY	150.00	-
	TO ALIGN FRONT FORK.	NOT NECESSARY	60.00	-
	TRANSPORT MOTORCYCLE TO WORKSHOP FOR REPAIRS .	NOT NECESSARY	60.00	-
			780.00	300.00
	GRAND TOTAL		3,819.10	2,547.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CC4/ASM22012688/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.