

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22012699/Kvp3e2
	8 SHENTON WAY SINGAPORE 0688		Date:	22/12/2022	
	ATTN: ANG YVON	NE		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 8592M	Veh. Inspected	ł	GBH 1090S
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S2M04GP7	Excess (\$)		0.00
	Assign From	ANG YVONNE	Assign Date		19/12/2022
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 (M)	c.c		1461
	Engine No.	HIDDEN	Year of Reg.		2017
	Chassis No.	VSKYBAM20Z0150959	Colour		WHITE
	Odometer	171819 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	185/70 R14	LAUFENN		9 mm
	L/H Front Tyre	185/70 R14	LAUFENN		9 mm
	R/H Rear Tyre	185/70 R14	HANKOOK		5 mm
	L/H Rear Tyre	185/70 R14	HANKOOK		5 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
5.	. General Information				
	Accident Date	17/12/2022	Inspect Date /	Time	20/12/2022 (09:38 AM)
	Survey held at	MJE MOTOR			
	BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642				
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22012699/Kvp3e2

Inspected By

KONG SENG CHEONG

K.K.LAU CPT(RET)

Licensed Appraiser BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser