



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 8405X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FORK @\$195.00	BENT	390.00	390.00
1	FRONT MUDGUARD	CUT	99.00	99.00
1	HANDLE BAR	NOT NECESSARY	68.00	-
1	FRONT BRAKE LEVER	CUT	18.00	18.00
1	HANDLE GRIP	NOT NECESSARY	25.00	-
1	STEERING CONE	NECESSARY	95.00	95.00
1	FRONT WHEEL SHAFT	NOT NECESSARY	25.00	-
	LESS 10% DISCOUNT		-	-60.20
			720.00	541.80
LABOUR				
	ALIGNMENT.		80.00	30.00
	TOWING.		50.00	30.00
	LABOUR.		120.00	120.00
			250.00	180.00
GRAND TOTAL			970.00	721.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				550.00

Report Ref No. CS/ASM22012704/Gnp3m4

Workshop did not agree with our adjustment.
He mentioned that he will liaise with the owner.

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.