2/8/23, 9:40 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22012706/RVP3M4

Singapore 079909 **Date:** 08/02/2023

REFERENCE

Insured/Claimant: HARTONO HALIM Policy No: DMPCSNW00220142200

Date of Loss: 22/10/2022 Nature of Claim: OD Claim No: SNM22D207613/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ899D

 Make & Model:
 BMW 520I, 2.0 LUXURY ADAP LED HL (A)
 Engine No:
 23226273B48B20A

 Reg. Date:
 30/08/2021 (Man. Year: 2020)
 Chassis No:
 WBA72AG050WX07884

Colour: White Odometer: 272 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: S\$226,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19 Rear Tyre Size: 245/40 R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------------------------|------------|------------|------------|--------|
| Parts | | 1,966.15 | 40.00 | 1,926.15 | 97.97 |
| Miscellaneous Items | | 0.00 | 0.00 | 0.00 | |
| Labour | | 2,667.00 | 2,172.00 | 495.00 | 18.56 |
| Paintwork Labour | | 0.00 | 0.00 | 0.00 | |
| Towing | | 0.00 | 0.00 | 0.00 | |
| | Calculated Gross Total (S\$) | 4,633.15 | 2,212.00 | 2,421.15 | 52.26 |
| | - Excess (S\$) | 750.00 | 750.00 | 0.00 | 0.00 |
| | (S\$) | 3,883.15 | 1,462.00 | 2,421.15 | 62.35 |
| | + GST 8.00/8.00% (S\$) | 310.65 | 116.96 | 193.69 | 62.35 |
| | Nett Amount (S\$) | 4,193.80 | 1,578.96 | 2,614.84 | 62.35 |

INSPECTION

Date of Assignment: 19/12/2022

Performance Motors Limited (Alexandra)

Date Inspected: 22/12/2022 Inspected At: 303 Alexandra Road, Sime Darby Performance

Centre

Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/8/23, 9:40 AM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Feb 2023)

Parts: 143 BMW 520I 2.0 LUXURY ADAP LED HL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKQ899D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty Part No. | Particulars | Condition | Repairer's | Amount |
|-------|----------------------|-------------------------------|-----------------------|-------------|-----------|
| 1 | 1 | *REAR LH GUIDE | Not Necessary | 179.90 FS | *- FS |
| 2 | 1 | *REAR BUMPER TRIM PANEL (PDC/ | Repair | 1,664.50 FS | *- FS |
| 3 | 1 | *REAR LH REAR REFLECTOR | Not Necessary | 41.75 FS | *- FS |
| 4 | 1 | *SUNDRIES | Necessary | 80.00 FS | *40.00 FS |
| F=Fra | anchise part. S=SpcN | ett. | Total Parts (Cf.) | 4 066 45 | 40.00 |
| | | | Total Parts (S\$) | 1,966.15 | 40.00 |
| | | Poport was unsubmitted | during this print out | | ſ |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|---|------------|------------|----------|
| <u>Lab</u> | <u>our Items</u> | | | |
| 1 | TO REPLACE REAR BUMPER | New | 1,275.00 | 850.00 |
| 2 | TO RESPRAY REAR BUMPER | New | 1,038.00 | 986.00 |
| 3 | TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION | New | 177.00 | 168.00 |
| 4 | TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION | New | 177.00 | 168.00 |
| | Gross Labour Cost (S\$) | | 2,667.00 | 2,172.00 |
| | Report was unsubmitted during this p | orint-out. | | |

< END OF ESTIMATES >