4/11/23, 11:20 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22012709/KWP3Q2

Singapore 079909 **Date:** 11/04/2023

REFERENCE

Insured/Claimant: Hong Guoyao Gabriel Policy No: DMPCSNW00234082100

Date of Loss: 13/12/2022 Nature of Claim: OD Claim No: SNM22D208995/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNB4623A

Make & Model: TOYOTA FORTUNER, 2.7 (A) Engine No: 2TR6840869

Reg. Date: 02/02/2010 (Man. Year: 2010) Chassis No: MR0ZX69G800023260

Colour: Metallic Pearl White Odometer: 139362 km

Engine Capacity: 2694 cc

Market Value/New Car

Price: S\$39,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 265/50 R20 Rear Tyre Size: 265/50 R20
Front Left Side: OTANI 6 mm Rear Left Side: Falken 8 mm
Front Right Side: OTANI 6 mm Rear Right Side: Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		11,155.00	9,930.00	1,225.00	10.98
Miscellaneous Items		200.00	485.00	-285.00	-142.50
Labour		970.20	1,024.80	-54.60	-5.63
Paintwork Labour		698.95	670.97	27.98	4.00
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,024.15	12,110.77	913.38	7.01
	Approved Total (Overridden) (S\$)		9,650.00		
	- Excess (S\$)	0.00	2,000.00	-2,000.00	
	(S\$)	13,024.15	7,650.00	5,374.15	41.26
	+ GST 7.00/8.00% (S\$)	911.69	612.00	299.69	32.87
	Nett Amount (S\$)	13,935.84	8,262.00	5,673.84	40.71

INSPECTION

Date of Assignment: 19/12/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 20/12/2022 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/11/23, 11:20 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Apr 2023)

Parts: 192 TOYOTA FORTUNER 2.7 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNB4623A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 F=Franchise part.	*Parts		11,155.00 F	*9,930.00 F
T – Francisse part.		Total Parts (S\$)	11,155.00	9,930.00
	Repo	rt was unsubmitted during this print-out		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 Misc		200.00	485.00
	Sub Total (S\$)	200.00	485.00
Recommended Labour			
No Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour			
1 Labour for paintwork	New	698.95	670.97
<u>Labour Items</u>			
2 Labour for panel/mechanical	New	970.20	1,024.80
	Gross Labour Cost (S\$)	1,669.15	1,695.77

< END OF ESTIMATES >

Report was unsubmitted during this print-out.