

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012710/AVP3Q2**Date:** 20/02/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00011272200

Claimant Vehicle No : SLC9371L **Insured Vehicle No :** PD125M

Date of Loss: 14/12/2022 Nature of Claim: TP Claim No: SNM22D209067/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLC9371L**

Make & Model: NISSAN NOTE, 1.2 (A) Engine No: HR12185227B

Reg. Date: 30/05/2016 (Man. Year: 2016) Chassis No: JN1TBAE12Z0982491

Colour: Blue Odometer: 116241 km

Engine Capacity: 1198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,889.72	2,551.68	4,338.04	62.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,040.00	1,710.00	62.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,639.72	3,591.68	6,048.04	62.74
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	9,639.72	2,850.00	6,789.72	70.43
+ GST 8.00/8.00% (S\$)	771.18	228.00	543.18	70.43
Nett Amount (S\$)	10,410.90	3,078.00	7,332.90	70.43

INSPECTION

Date of Assignment: 19/12/2022

Date Inspected: 20/12/2022 Inspected At: Autobacs Car Care (Singapore) Pte Ltd (HQ)
8 Kaki Bukit Ave 4,, #08-45/46 Premier@Kaki
Bukit,
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2023)
Parts:	144	NISSAN NOTE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9371L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Not Necessary	560.40 FL	*- FL
2	1		*FRONT FENDER INNER INNER SHIELD	Not Necessary	120.60 FL	*- FL
3	1		*FRONT DOOR LH	Dented	960.30 FL	*960.30 FL
4	1		*FRONT DOOR GLASS OUTER MOULDING LH	Not Necessary	160.50 FL	*- FL
5	1		*FRONT DOOR BLACK FRAME STICKER VERTICAL LH	Necessary	48.00 FL	*48.00 FL
6	1		*FRONT DOOR HINGE TOP LH	Not Necessary	86.20 FL	*- FL
7	1		*FRONT DOOR HINGE BOTTOM LH	Not Necessary	86.20 FL	*- FL
8	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	695.70 FL	*- FL
9	1		*FRONT DOOR POWER WINDOW REGULATOR LH	Not Necessary	160.90 FL	*- FL
10	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	580.80 FL	*- FL
11	1		*FRONT DOOR MECHANISM LOCK LH	Damaged	260.60 FL	*260.60 FL
12	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	130.70 FL	*- FL
13	1		*REAR DOOR LH	Distorted	980.60 FL	*980.60 FL
14	1		*REAR DOOR GLASS OUTER MOULDING LH	Not Necessary	130.60 FL	*- FL
15	1		*REAR DOOR BLACK FRAME FRONT STICKER LH	Necessary	56.20 FL	*56.20 FL
16	1		*REAR DOOR BLACK FRAME REAR STICKER LH	Necessary	56.20 FL	*56.20 FL
17	1		*REAR DOOR HINGE TOP LH	Bent	86.80 FL	*86.80 FL
18	1		*REAR DOOR HINGE BOTTOM LH	Not Necessary	86.80 FL	*- FL
19	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	630.50 FL	*- FL
20	1		*REAR DOOR POWER WINDOW REGULATOR LH	Not Necessary	165.20 FL	*- FL
21	1		*REAR DOOR POWER WINDOW MOTOR LH	Not Necessary	585.30 FL	*- FL
22	1		*REAR DOOR MECHANISM LOCK LH	Not Necessary	264.50 FL	*- FL
23	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	130.70 FL	*- FL
24	1		*SIDE MIRROR LH	Damaged	386.50 FL	*386.50 FL
25	1		*FRONT FENDER INNER SHIELD CLIPS SET LH	Not Necessary	60.00 FS	*- FS
26	1		*FRONT DOOR INNER TRIM BOARD CLIPS SET LH	Not Necessary	80.00 FS	*- FS
27	1		*REAR DOOR INNER TRIM BOARD CLIPS SET LH	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,630.80	2,835.20
- List Item Discount on L Items 10.00/10.00% (\$)	741.08	283.52
Total Parts (\$)	6,889.72	2,551.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,000.00	400.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	800.00	500.00
3	TO PERFORM CONDUCT WATER LEAKAGE WATER TEST OF ACCIDENT PORTION	New	80.00	0.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	150.00	40.00
5	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	New	250.00	0.00
6	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	120.00	100.00
7	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	350.00	0.00
Gross Labour Cost (S\$)			2,750.00	1,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >