

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22012715/UQP3Q2**Date:** 06/01/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW0027422202	
<b>Claimant Vehicle No :</b>	SMG1985K	<b>Insured Vehicle No :</b>	SKZ7557Y	
Date of Loss:	14/12/2022	Nature of Claim:	TP	Claim No: SNM22D209057/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMG1985K</b>		Engine No:	4B40DX9271
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 (A)		Chassis No:	JMAXTGK1WJZ004143
Reg. Date:	10/12/2018 (Man. Year: 2018)		Odometer:	154026 km
Colour:	Silver			
Engine Capacity:	1499 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,879.00	7,173.40	5,705.60	44.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,170.00	2,620.00	2,550.00	49.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,049.00</b>	<b>9,793.40</b>	<b>8,255.60</b>	<b>45.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>18,049.00</b>	<b>7,800.00</b>	<b>10,249.00</b>	<b>56.78</b>

**INSPECTION**

Date of Assignment:	19/12/2022		
Date Inspected:	20/12/2022	Inspected At:	Cheng Motor Work Company (HQ) NO.1 KAKI BUKIT AVE 6 #01-83 Singapore 417883
Estimated Period of Repair:	7.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jan 2023)
Parts:	143	MITSUBISHI ECLIPSE CROSS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG1985K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	942.00 F	*942.00 FN
2	1		*TAILGATE EMBLEM ECLIPSE WITH CROSS	Not Necessary	86.00 F	*- FN
3	1		*TAILGATE EMBLEM MIVEC	Not Necessary	90.00 F	*- FN
4	1		*TAILGATE LOGO	Not Necessary	40.00 F	*- FN
5	1		*TAILGATE CENTER CHROME	Not Necessary	483.00 F	*- FN
6	1		*TAILGATE C&C PLATE	Not Necessary	45.00 F	*- FN
7	1		*TAILGATE INNER TRIM	Torn	483.00 F	*345.00 FN
8	10		*TAILGATE INNER TRIM SCREW	Not Necessary	100.00 F	*- FN
9	1		*TAILGATE INNER LOCK	Dented / Jammed	379.00 F	*280.00 FN
10	1		*TAILGATE LOWER LOCK	Not Necessary	20.00 F	*- FN
11	1		*TAILGATE WEATHERSTRIP	Twisted	192.00 F	*192.00 FN
12	1		*REAR BUMPER TOP	Distorted	605.00 F	*605.00 FN
13	1		*BUMPER REINFORCEMENT (IMPACT BAR)	Bent	489.00 F	*489.00 FN
14	2		*BUMPER SIDE RETAINER	Bent	56.00 F	*56.00 FN
15	2		*BUMPER BRACKET SIDE	Bent	58.00 F	*58.00 FN
16	1		*SET BUMPER CLIP	Necessary	75.00 F	*45.00 FN
17	10		*BUMPER REVERT	Not Necessary	40.00 F	*- FN
18	1		*BUMPER LOWER	Distorted	150.00 F	*150.00 FN
19	1		*BUMPER LOWER LIP	Distorted	280.00 F	*280.00 FN
20	2		*BUMPER SPONGE	Torn	96.00 F	*96.00 FN
21	1		*BUMPER REFLECTOR LAMP L/H	Cracked	116.00 F	*116.00 FN
22	1		*BUMPER REFLECTOR LAMP R/H	Cracked	131.00 F	*131.00 FN
23	2		*BUMPER LOWER GARNISH SILVER COLOUR	Distorted	232.00 F	*232.00 FN
24	10		*BUMPER LOWER GARNISH CLIP	Necessary	60.00 F	*60.00 FN
25	1		*REAR END PANEL	Badly Dented	486.00 F	*475.00 FN
26	1		*END PANEL EXTENSION	O/S Dented / N/S Repair	276.00 F	*138.00 FN
27	1		*END PANEL TOP GARNISH	Twisted	129.00 F	*129.00 FN
28	1		*FLOOR COVER TOP	Warped	380.00 F	*380.00 FN
29	1		*CARGO BOX	Warped / Cracked	367.00 F	*367.00 FN
30	4		*REVERSE SENSOR	Shorted (3 PCS ONLY)	1,304.00 F	*690.00 FN
31	1		*REAR EXHAUST SILENCE	Dented / Bent	521.00 F	*521.00 FN
32	1		*TOW HOOD	Torn	95.00 F	*95.00 FN
33	2		*REAR MUDGUARDS PROTECTOR	Torn	288.00 F	*288.00 FN
34	1		*REAR RIGHT SIDE MUDGUARDS	Repair	892.00 F	*- FN
35	1		*TAILGATE CENTER GARNISH	Not Necessary	483.00 F	*- FN
36	2		*TAIL LAMP	Not Necessary	1,366.00 F	*- FN
37	1		*REAR MUDGUARD INNER TRIM (O/S)	Deformed	544.00 F	*366.00 FN
38	1		*REVERSE SENSOR WIRE HARDNESS	Torn	150.00 F	*150.00 FN
39	1		*REAR BUZZLE	Cracked	130.00 F	*130.00 FN
40	1		*KEYLESS SENSOR	Cracked	120.00 F	*120.00 FN
41	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (\$\$)					12,879.00	7,966.00
- Nett Item Discount on N Items 0.00/10.00% (\$\$)					0.00	792.60
Total Parts (\$\$)					12,879.00	7,173.40
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR KNOCKING FLOOR PANEL,WELDING ,CUTTING ,REPAIRING AND REPLACEMENT OF PARTS	New	2,000.00	1,000.00
2	TO SPRAY PAINT ON THE DAMAGE PARTS	New	1,800.00	1,100.00
3	TO SPRAY RUST-PROOFING	New	200.00	80.00
4	TO REMOVE/TRANSFER BOOTH LID MECHANICAL	New	150.00	60.00
5	TO REMOVE/REFIT REAR WINDSCREEN GLASS	New	200.00	120.00
6	TO CHECK WIRING AND CHARGE WIRE HARNESS	New	120.00	30.00
7	TO REMOVE/RENEW REVERSE SENSOR }	New	150.00	50.00
8	TO RE-PROGRAM REVERSE SENSOR /CAMERA }	New	150.00	0.00
9	TO CLEAN UP INTERNAL SEAT ,INNER TRIM }	New	150.00	80.00
10	TO REMOVE/REFIT INTERNAL SEAT ,INNER TRIM }	New	150.00	0.00
11	REMOVE/REFIX REAR W/SCREEN GLASS LOWER	New	100.00	100.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,170.00</b>	<b>2,620.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >