

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012718/AQP3E2**Date:** 30/03/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00098252200
Claimant Vehicle No :	SJZ3737H	Insured Vehicle No :	SJP9779A
Date of Loss:	19/12/2022	Nature of Claim:	TP
		Claim No:	SNM22D209107/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ3737H	Engine No:	27186030032470
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2073472F034691
Reg. Date:	04/05/2010 (Man. Year: 2010)	Odometer:	153480 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,080.70	9,450.30	3,630.40	27.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,080.00	1,610.00	1,470.00	47.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,160.70	11,060.30	5,100.40	31.56
Approved Total (Overridden) (S\$)		8,800.00		
(S\$)	16,160.70	8,800.00	7,360.70	45.55
+ GST 8.00/8.00% (S\$)	1,292.86	704.00	588.86	45.55
Nett Amount (S\$)	17,453.56	9,504.00	7,949.56	45.55

INSPECTION

Date of Assignment:	19/12/2022	
Date Inspected:	20/12/2022 Inspected At:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Mar 2023)
Parts:	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ3737H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID AMG EMBLEM	Necessary	187.00 FL	*187.00 FL
2	1		*REAR BOOTLID E250 EMBLEM	Necessary	177.00 FL	*177.00 FL
3	1		*REAR BOOTLID LOGO EMBLEM	Necessary	99.00 FL	*99.00 FL
4	1		*REAR BOOTLID (ALUMINIUM)	Dented	2,819.00 FL	*2,275.00 FL
5	1		*REAR BOOTLID MECHANISM LOCK	Damaged	469.00 FL	*469.00 FL
6	1		*REAR BOOTLID MECHANISM LOCK GARNISH	Not Necessary	298.00 FL	*- FL
7	1		*REAR BOOTLID REFLECTOR L/R	O/S Cracked	992.00 FL	*496.00 FL
8	1		*REAR BOOTLID WEATHER STRIP	Cut	269.00 FL	*269.00 FL
9	2		*REAR BUMPER CHROME TAIL L/R (AMG)	Damaged	650.00 FN	*500.00 F
10	1		*REAR BUMPER REINFORCEMENT	Dented	799.00 FL	*799.00 FL
11	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Damaged (2Pc Only)	860.00 FL	*430.00 FL
12	4		*REAR BUMPER REVERSE SENSOR O RING	Necessary	80.00 FL	*80.00 FL
13	4		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	112.00 FL	*112.00 FL
14	2		*REAR BUMPER SIDE RETAINER L/R	Damaged	158.00 FL	*158.00 FL
15	1		*REAR END PANEL	Repair	789.00 FL	*- FL
16	1		*REAR END PANEL INNER TOP GARNISH	Cracked	158.00 FL	*158.00 FL
17	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	90.00 FL	*- FL
18	1		*REAR EXHAUST SILENCER BOX	Bent	1,659.00 FN	*900.00 F
19	2		*REAR TAILLAMP L/R	Cracked	1,508.00 FL	*1,508.00 FL
20	2		*REAR TAILLAMP LOWER BRACKET L/R	Cracked	150.00 FL	*150.00 FL
21	1		*REAR BOOTLID NUMBER PLATE	Not Necessary	90.00 FS	*- FS
22	1		*REAR BOOTLID NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
23	1		*REAR BUMPER (AMG) ASSY	Distorted	1,800.00 FS	*1,400.00 FS
24	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	14,313.00	10,187.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,001.40	736.70
- Nett Item Discount on N Items 10.00/0.00% (S\$)	230.90	0.00
Total Parts (S\$)	13,080.70	9,450.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER REAR BOOTLID MECHANISM LOCK OUTER HANDLE REFLECTOR	New	80.00	60.00
2	TO RESET SYSTEM AFTER REPAIR WORKS	New	400.00	0.00
3	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	60.00
4	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	100.00	60.00
5	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR POTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	700.00
6	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	100.00	80.00
7	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	50.00
Gross Labour Cost (S\$)			3,080.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >