

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122012720/AVY3M4**Date:** 03/03/2023**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SNA6378A **Insured Vehicle No :** XE2641B

Date of Loss: 19/12/2022 Nature of Claim: TP Claim No: CDMCG22002741

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA6378A**

Make & Model: MITSUBISHI OUTLANDER, 2.4 CVT AWD S/R FACELIFT (A) Engine No: 4B12QJ3492

Reg. Date: 05/11/2015 (Man. Year: 2015) Chassis No: JMYXTGF3WGW001699

Colour: Silver Odometer: 121210 km

Engine Capacity: 2360 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,074.39	6,792.03	9,282.36	57.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,100.00	3,580.00	63.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	21,754.39	8,892.03	12,862.36	59.13
Approved Total (Overridden) (\$\$)		7,100.00		
Nett Amount (\$\$)	21,754.39	7,100.00	14,654.39	67.36

INSPECTION

Date of Assignment: 20/12/2022

Date Inspected: 20/12/2022 Inspected At: HD PERFECT AUTOWORK PTE LTD
8 KAKI BUKIT AVENUE 4, #08-09
PREMIER @ KAKI BUKIT, SINGAPORE 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2023)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.4 CVT AWD S/R FACELIFT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA6378A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	884.00 FL	*884.00 FL
2	1		*TAILGATE LOGO	Necessary	41.00 FL	*41.00 FL
3	1		*TAIL GATE EMBLEM MIVEC	Necessary	52.00 FL	*52.00 FL
4	1		*TAILGATE EMBLEM OUTLANDER	Necessary	86.00 FL	*86.00 FL
5	1		*TAIL GATE OUTER GARNISH (CHROME)	Cracked	446.00 FL	*446.00 FL
6	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	173.00 FL	*- FL
7	2		*TAIL GATE LAMP	Cracked	794.00 FL	*794.00 FL
8	1		*TAILGATE INNER LOCK	Damaged	428.00 FL	*428.00 FL
9	1		*TAILGATE WEATHER STRIP	Cut	192.00 FL	*192.00 FL
10	4		*TAILGATE STOPPER	Not Necessary	72.00 FL	*- FL
11	1		*TAILGATE INNER TRIM (TOP)	Cracked	238.40 FL	*238.40 FL
12	1		*TAILGATE AUTO SYSTEM MOTOR	Not Necessary	981.60 FL	*- FL
13	2		*TAILGATE SIDE SENSOR	Not Necessary	1,370.60 FL	*- FL
14	2		*TAIL GATE DAMPER	Not Necessary	340.00 FL	*- FL
15	1		*TAIL GATE WIPER ARM	Not Necessary	170.00 FL	*- FL
16	1		*TAIL GATE WIPER ARM BOLT COVER	Not Necessary	19.80 FL	*- FL
17	1		*TAIL GATE WIPER BLADE	Not Necessary	97.80 FL	*- FL
18	1		*TAIL GATE WIPER MOTOR	Not Necessary	790.60 FL	*- FL
19	1		*TAILGATE DETECTOR WIREHARNESS	Not Necessary	498.00 FL	*- FL
20	1		*TAILGATE DETECTOR	Not Necessary	396.00 FL	*- FL
21	1		*TAILGATE BUZZER	Cracked	182.30 FL	*182.30 FL
22	1		*TAILGATE WINDSCREEN MOULDING	Necessary	160.00 FL	*160.00 FL
23	1		*REAR BUMPER	Deformed	816.00 FL	*816.00 FL
24	2		*REAR BUMPER SIDE ARCED GARNISH	Not Necessary	588.00 FL	*- FL
25	2		*REAR BUMPER LAMP	Not Necessary	196.00 FL	*- FL
26	1		*REAR BUMPER LAMP WIRE HARNESS	Not Necessary	387.00 FL	*- FL
27	1		*REAR BUMPER LOWER CENTER GARNISH	Deformed	269.00 FL	*269.00 FL
28	2		*REAR BUMPER SIDE RETAINER	Damaged	64.00 FL	*64.00 FL
29	2		*TAIL LAMP	Cracked	1,142.00 FL	*1,012.00 FL
30	2		*REAR FENDER INNER COWLING	Not Necessary	306.00 FL	*- FL
31	2		*REAR FENDER INNER TRIM	Not Necessary	1,854.00 FL	*- FL
32	1		*REAR END PANEL	Dented	496.00 FL	*496.00 FL
33	1		*REAR END PANEL TOP GARNISH	Deformed	146.00 FL	*146.00 FL
34	1		*REAR STORAGE COMPARTMENT GARNISH	Deformed	455.00 FL	*455.00 FL
35	1		*REAR TOOLS COMPARTMENT COVER	Deformed	185.00 FL	*185.00 FL
36	2		*REAR CHASSIS AND ABSORD PANEL	Repair	210.00 FL	*- FL
37	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
38	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
39	1		*SET REAR BUMPER SIDE ARCED GARNISH CLIP	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR BUMPER CENTER GARNISH CLIP	Necessary	80.00 FS	*20.00 FS
41	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
42	1		*TAILGATE EMBLEM C&C	Necessary	180.00 FS	*50.00 FS
43	1		*SET TAILGATE INNER TRIM (TOP) CLIP	Not Necessary	60.00 FS	*- FS
44	1		*SET TAILGATE INNER TRIM (SIDE) CLIP	Not Necessary	60.00 FS	*- FS
45	1		*SET TAILGATE INNER TRIM (LOWER) CLIP	Necessary	60.00 FS	*30.00 FS
46	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

3/3/23, 9:06 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
48	1		*SET TAILLAMP CLIP	Necessary	40.00 FS	*20.00 FS
49	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
50	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
51	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
52	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
53	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
54	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,627.10	7,486.70
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,552.71	694.67
Total Parts (\$\$)					16,074.39	6,792.03
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	New	2,000.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR	New	250.00	60.00
6	REMOVE AND REPLACE VIDEO RECORDER	New	80.00	50.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
9	REINSTALL AND RESET TAILGATE AUTO SYSTEM MOTOR & SENSOR	New	350.00	0.00
10	TRANSFER TAILGATE MECHANISM	New	80.00	80.00
11	CONDUCT WATER LEAKAGE TEST	New	180.00	0.00
12	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	120.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	New	200.00	0.00
Gross Labour Cost (\$\$)			5,680.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >