

Vehicle Damage Assessment Report for [SNA6378A]

Estimate Created: 02/03/2023 03:24 by Insurlogic 1 (Insurlogic_Pte_Ltd)

Owned: 02/03/2023 03:46 by Insurlogic 1 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO INSURANCE	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Mitsubishi	Model	Outlander
Engine Type			
License Plate Number	SNA6378A	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- Final review base on information provide by LKK: Concluded the cost of repair at lump sum \$7100.00 with 6 days for repair

Insurlogic 1 (02/03/2023 03:46)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
TAILGATE		1	884.00	-10.00 %	795.60
TAILGATE LOGO		1	41.00	-10.00 %	36.90
TAILGATE EMBLEM MIVAC		1	52.00	-10.00 %	46.80
TAILGATE EMBLEM OUTLANDER		1	86.00	-10.00 %	77.40
TAILGATE OUTER GARNISH		1	446.00	-10.00 %	401.40
TAILGATE LAMP		1	794.00	-10.00 %	714.60
TAILGATE INNER LOCK		1	428.00	-10.00 %	385.20
TAILGATE WEATHERSTRIP		1	192.00	-10.00 %	172.80
TAILGATE INNER TRIM TOP		1	238.40	-10.00 %	214.56
TAILGATE BUZZER		1	182.30	-10.00 %	164.07
TAILGATE WINDSCREEN MOULDING		1	160.00	-10.00 %	144.00
REAR BUMPER		1	816.00	-10.00 %	734.40
REAR BUMPER LOWER CTR GARNISH		1	269.00	-10.00 %	242.10
REAR BUMPER SIDE RETAINER		1	64.00	-10.00 %	57.60
TAILLAMP		1	1012.00	-10.00 %	910.80
REAR END PANEL		1	496.00	-10.00 %	446.40
REAR END PANEL TOP GARNISH		1	146.00	-10.00 %	131.40
REAR STORAGE COMPARTMENT GARNISH		1	455.00	-10.00 %	409.50
REAR TOOLS COMPARTMENT COVER		1	185.00	-10.00 %	166.50

Parts Subtotal 6,252.03

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR NUMBER PLATE		1.0	50.00	0.00 %	50.00
REAR BUMPER CLIPS		1.0	30.00	0.00 %	30.00
REAR CTR GARNISH CLIPS		1.0	20.00	0.00 %	20.00
C&C EMBLEM		1.0	50.00	0.00 %	50.00
TAILGATE INNER		1.0	30.00	0.00 %	30.00

REAR WINDSCREEN SEALANT	1.0	40.00	0.00 %	40.00
TAILGATE WINDSCREEN INNER SHIELD	1.0	30.00	0.00 %	30.00
TAILLAMP CLIPS	1.0	20.00	0.00 %	20.00
REAR END PANEL INSULATION SEAL	1.0	60.00	0.00 %	60.00
REAR END PANEL TOP GARNISH CLIPS	1.0	10.00	0.00 %	10.00
REVERSE SENSOR	1.0	200.00	0.00 %	200.00

Materials Subtotal 540.00

Labor

Replace/RnR

Description	Type	Cost	Markup/Disc %	Price
REPLACE/REPAIR ACCIDENT AFFECTED ITEMS AND AREAS	RnR	800.00	0.00 %	800.00
TUFF COAT	RnR	60.00	0.00 %	60.00
WIRE CHECK	RnR	30.00	0.00 %	30.00
RNR INTERIOR	RnR	60.00	0.00 %	60.00
RNR VIDEO RECORDER	RnR	50.00	0.00 %	50.00
RNR REVERSE SENSORS	RnR	50.00	0.00 %	50.00
RNR REVERSE CAM	RnR	50.00	0.00 %	50.00
TRANSFER TAILGATE MECHNISM	RnR	80.00	0.00 %	80.00
RNR REAR WINDSCREEN	RnR	120.00	0.00 %	120.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
PAINT ON ACCIDENT AFFECTED AREAS	Full spray	800.00	0.00 %	800.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,300.00

Paint Labor Subtotal 800.00

Labor Subtotal 2,100.00

Summary

Repair Cost 8,892.03

Discount(20 %) (1,792.03)

7,100.00

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 7,100.00