

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22012721/UWY3Q2**Date:** 28/02/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

Claimant Vehicle No : XD2213J**Insured Vehicle No :** GBC1994K

Date of Loss: 29/11/2022

Nature of Claim: TP

Claim No: 2022 22008804JK

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **XD2213J**

Make & Model: HINO FS1ELKD, 12.9 D (M)

Engine No: E13CUN10794

Reg. Date: 12/02/2008 (Man. Year: 2007)

Chassis No: JHDFS1ELKXXX10083

Colour: Pink/Blue

Odometer: 434594 km

Engine Capacity: 12913 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D/D)

Front Left Side: Golden Crown 6 mm

Rear Left Side: Firenza 6/6/6 mm

Front Right Side: Golden Crown 6 mm

Rear Right Side: Firenza 6/6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	65,000.00	30,000.00	35,000.00	53.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	65,000.00	30,000.00	35,000.00	53.85
+ GST 7.00/7.00% (S\$)	4,550.00	2,100.00	2,450.00	53.85
Nett Amount (S\$)	69,550.00	32,100.00	37,450.00	53.85
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 20/12/2022

Date Inspected: 27/12/2022 Inspected At:

Mah Lian Motor Vehicle Repairer (HQ)

NO. 38 DEFU LANE 9

Singapore 539278

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 28 Feb 2023)	
Parts:	N/A	HINO FS1ELKD 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD2213J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TMA ASSY W/LABOUR (\$60,000.00) (50%)	New	65,000.00	30,000.00
Gross Labour Cost (\$\$)			65,000.00	30,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >