

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS22012722/AVY3E2**Date:** 06/03/2023REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No :

GBC5290G

Insured Vehicle No :

SGF4409P

Date of Loss: 17/12/2022

Nature of Claim:

TP

Claim No:

DMPC2200636H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBC5290G**

Make & Model: TOYOTA DYNA 150 MANUAL 3SEATER, 3.0 D (M) Engine No: 1KD2240714

Reg. Date: 22/11/2012 (Man. Year: 2012)

Chassis No: JTFAT35Y10K202112

Colour: White

Odometer: 155772 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

155 R12C

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Tourador 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Tourador 6 mm

*The above values represent the remaining tyre treads depth*COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,349.90	2,699.20	2,650.70	49.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,190.00	610.00	33.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,149.90	3,889.20	3,260.70	45.60
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	7,149.90	3,100.00	4,049.90	56.64
+ GST 8.00/8.00% (S\$)	571.99	248.00	323.99	56.64
Nett Amount (S\$)	7,721.89	3,348.00	4,373.89	56.64

INSPECTION

Date of Assignment: 20/12/2022

Date Inspected: 23/12/2022 Inspected At:

ONE GARAGE PTE LTD (HQ)

8 KAKI BUKIT AVE 4 #03-33 PREMIER @ K. BUKIT

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Mar 2023)	
Parts:	N/A	TOYOTA DYNA 150 MANUAL 3SEATER 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC5290G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
2	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
3	1		*REAR NUMBER PLATE LAMP	Not Necessary	68.70 F	*- FL
4	1		*REAR NUMBER PLATE BRACKET	Bent	160.40 F	*160.40 FL
5	1		*REAR STEP PANEL	Bent	300.00 FS	*200.00 FS
6	1		*REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
7	2		*TAILLAMP	Cracked	490.80 F	*490.80 FL
8	1		*TAILLAMP PANEL	O/S Bent	371.00 F	*185.50 FL
9	1		*STOPPER	O/S Cut	40.00 FS	*20.00 FS
10	1		*STOPPER BRACKET	O/S Bent	221.00 F	*110.50 FL
11	1		*TAILGATE	Dented	1,582.60 F	*1,582.60 FL
12	1		*TAILGATE SIDE LOCK	O/S Damaged	441.40 F	*220.70 FL
13	4		*TAILGATE HINGE	Not Necessary	257.60 F	*- FL
14	1		*TAILGATE LOWER MEMBER	Repair	495.40 F	*- FL
15	1		*TOYOTA STICKER	Necessary	155.10 F	*155.10 FL
16	1		*AR STICKER	Necessary	30.00 FS	*30.00 FS
17	1		*70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
18	1		*SPARE TYRE LOCK CHAIN	Not Necessary	385.90 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,349.90	3,425.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	726.40
Total Parts (\$\$)	5,349.90	2,699.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	800.00	600.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	60.00
Gross Labour Cost (\$\$)			1,800.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >