



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6986Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER EMBLEM	NECESSARY	88.00	88.00
1	FRONT BUMPER	CRACKED	586.18	586.18
1	FRONT BUMPER UPPER GRILLE	SERVICEABLE	301.90	-
1	FRONT BUMPER EXTENSION MTG PLATE	CRACKED	99.00	99.00
2	FRONT BUMPER BRACKET LH/RH @\$77.00	SERVICEABLE	154.00	-
	LESS 25% DISCOUNT		-307.27	-193.30
			921.81	579.88
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT NUMBER PLATE W/HOLDER (SN)	DEFORMED	55.00	55.00
			55.00	55.00
<b><u>LABOUR</u></b>				
	PANEL BEATING.		400.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
			700.00	600.00
<b>GRAND TOTAL</b>			<b>1,676.81</b>	<b>1,234.88</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>950.00</b>

Report Ref No. NS/INC22012723/Nnp3q2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.