

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC22012724/Nnp3e2	
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	13-01-2023 INC4	
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKP 313H	Veh. Ir	spected	SH 7177K
	Policy No.		Covera	age (\$)	0.00
	Claim No.	MT/1205042-001	Exces	s (\$)	0.00
	Assign From		Assigr	n Date	19/12/2022
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ G3	c.c		1798
	Engine No.	HIDDEN	Year o	f Reg.	2019
	Chassis No.	KMHC851CVLU188652	Coloui	•	BLUE
	Odometer	503046	Steering		IN ORDER
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST	_AKE	4 mm
	L/H Front Tyre	195/65 R15	WEST	_AKE	4 mm
	R/H Rear Tyre	195/65 R15	WEST	_AKE	5 mm
	L/H Rear Tyre	195/65 R15	WEST	_AKE	5 mm
4.	F. C.				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	17/12/2022	Inspec	tion Date	19/12/2022
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				