

ASS. REC. BY:

REF:

ASM / 22012727/KP

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of Linco Amk 01-45 050H

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 881K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA 390PRYr Regn: 01, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)Make: Toy Vellorc.c. 2382Colour: M. Black

A/C: Insured / Std / NI / NA

Sp. Reading: 200821

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AN14208349452Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size: CONTINENTAL235/50R18R: Pir

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 2 mmR/Bal. 3 mmL/Bal. 2 mmL/Bal. 3 mmD.O.A. 16/12/22D.O.I. 20/12/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Person-in-charge not in, no documents given

27/8 11:30 824501 Car

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee: _____

Transportation: _____

\$ - RS. \$

Fees: _____

Others: _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

*Not Authorized
11 Lnp @ 2450h
Resurvey After Paint
4 days*

Vehicle No: SNA3908R

Model: TOYOTA VELLFIRE

QTY	Description	Repairer's Estimate
	Spare Parts - List Items	
1	Rear tailgate	\$ <i>B</i> 1,800.00 <i>—</i>
1	Rear bumper <i>1136</i>	\$ <i>Bu</i> 1,600.00 <i>—</i>
1	Rear bumper towing cover	\$ <i>Bu</i> 350.00 <i>X</i>

251

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 3,750.00

\$ -

S/N. Labour Charges

1	Remove and refit and panel beating	\$	600.00	400
2	Remove, refit and replaced damage and check up rear electrical wiring	\$	150.00	200
3	Remove and refit inner garnishes trim to assist repair	\$	<i>na</i> 200.00	X
4	To apply undercoating on replaced panel	\$	120.00	300
5	To Respray Painting.	\$	800.00	400

\$ 1,870.00

GRAND TOTAL

\$ 5,620.00

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) _____
(Contact) _____
(Email) _____