

ASS. REC. BY:

REF:

Kenneth

ASM

/ 22012727/KP

C

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of Linko Amk 01-45 050H

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 8.81K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNA 390PR Yr Regn: 01, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or (A) WagonMake: Toy Vellor c.c. 2382Colour: M. Black A/C: Insured / Std / NI / NASp. Reading: 200821 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AN120 8349452Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD / AJRlm orTyre Size: Continental 235/50R18R: Pir

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 16/12/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

/ Pers-in-charge not sm, no documents given/ 17/12 11:30 824501 Car

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9773 6360

Email: mak.auburnauto@gmail.com

*Not Authored
11 Sep @ 2450h
Resurvey After Paint
4 days*

Vehicle No: SNA3908R

Model: TOYOTA VELLFIRE

QTY	Description
	Spare Parts - List Items
1	Rear tailgate
1	Rear bumper 1136
1	Rear bumper towing cover

Repairer's Estimate

\$	By	1,800.00	—
\$	Bu	1,600.00	—
\$	In	350.00	X

258

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 3,750.00

\$ -

S/N. Labour Charges

1	Remove and refit and panel beating	\$	600.00	40d
2	Remove, refit and replaced damage and check up rear electrical wiring	\$	150.00	2d
3	Remove and refit inner garnishes trim to assist repair	\$	na 200.00	X
4	To apply undercoating on replaced panel	\$	120.00	3d
5	To Respray Painting.	\$	800.00	44d

\$ 1,870.00

GRAND TOTAL

\$ 5,620.00

Page 2 of 3

Survey: 1st / 2nd / 3rd (delete accordingly)

Surveyor Details:

(Name) _____

(Contact) _____

(Email) _____