

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22012733/KYA3Q2**Date:** 12/05/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210079662
Claimant Vehicle No :	SHD9826J	Insured Vehicle No :	SJA1180H
Date of Loss:	16/12/2022	Nature of Claim:	TP
		Claim No:	9071288042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9826J		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2H77928
Reg. Date:	29/01/2021 (Man. Year: 2020)	Chassis No:	JTDKB3FU703093659
Colour:	Metallic Pearl White/Red	Odometer:	160302 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Grenlander 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Grenlander 9 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,213.90	4,342.12	3,871.78	47.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,100.00	1,490.00	3,610.00	70.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	13,313.90	5,832.12	7,481.78	56.20
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	19/12/2022		
Date Inspected:	19/12/2022	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL SUB-ASSY, FRONT DOOR, RH	Bent	1,300.70 FL	*1,300.70 FL
2	1		*FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	Repair	193.50 FL	*- FL
3	1		*HANDLE ASSY, FRONT DOOR, OUTSIDE RH	Serviceable	390.60 FL	*- FL
4	1		*MOTOR ASSY, POWER WINDOW REGULATOR, RH	Jammed	926.00 FL	*926.00 FL
5	1		*WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	Serviceable	321.10 FL	*- FL
6	1		*HINGE ASSY, FRONT DOOR, LOWER RH	Repair	110.60 FL	*- FL
7	1		*HINGE ASSY, FRONT DOOR, UPPER RH	Repair	97.50 FL	*- FL
8	1		*REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	Bent	238.30 FL	*238.30 FL
9	1		*TAPE, BLACK OUT, NO.2 FRT RH	Necessary	43.50 FL	*43.50 FL
10	1		*TAPE, BLACK OUT, NO.1 FRT RH	Necessary	13.30 FL	*13.30 FL
11	1		*TAPE, BLACK OUT, NO.3 FRT RH	Necessary	26.30 FL	*26.30 FL
12	1		*PANEL SUB-ASSY, REAR DOOR, RH	Bent	1,294.90 FL	*1,294.90 FL
13	1		*FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	Serviceable	193.50 FL	*- FL
14	1		*HANDLE ASSY, REAR DOOR OUTSIDE, RH	Serviceable	97.40 FL	*- FL
15	1		*WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	Serviceable	293.00 FL	*- FL
16	1		*MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	Serviceable	926.00 FL	*- FL
17	1		*REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	Serviceable	206.70 FL	*- FL
18	1		*TAPE, BLACK OUT, NO.2 REAR RH	Necessary	34.90 FL	*34.90 FL
19	1		*TAPE, BLACK OUT, NO.3 REAR RH	Necessary	15.40 FL	*15.40 FL
20	1		*TAPE, BLACK OUT, NO.1 REAR RH	Necessary	21.90 FL	*21.90 FL
21	1		*HINGE ASSY, REAR DOOR, LOWER RH	Distorted	87.10 FL	*87.10 FL
22	1		*HINGE ASSY, REAR DOOR, UPPER RH	Repair	98.90 FL	*- FL
23	1		*FENDER SUB-ASSY, FRONT RH	Bent	977.80 FL	*977.80 FL
24	1		*EMBLEM, SIDE PANEL, RH	Necessary	54.60 FL	*54.60 FL
25	1		*LINER, FRONT FENDER, LH	Serviceable	210.30 FL	*- FL
26	1		*MIRROR ASSY, OUTER REAR VIEW, RH	Serviceable	1,436.60 FL	*- FL
27	1		*MOULDING ASSY, BODY ROCKER PANEL, RH	Buckled / Dented	594.80 FL	*594.80 FL
28	1		*FRT FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
29	1		*FRT BUMPER CLIP	Not Necessary	65.00 FS	*- FS
30	1		*FRT BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
31	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	*60.00 FS
32	1		*DOOR STICKER TEL. NO	Necessary	100.00 FS	*60.00 FS
33	1		*DOOR TRIM CLIP	Not Necessary	75.00 FS	*- FS
34	1		*DOOR WEATHERSTRIP CLIP	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,765.20	5,749.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,551.30	1,407.38
Total Parts (\$\$)	8,213.90	4,342.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	90.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,600.00	500.00
4	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	-
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	880.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,100.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >