

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22012735/RVY3E2**Date:** 02/03/2023**REFERENCE**

Insured/Claimant:	THIA CHEE CHEW	Policy No:	7210079662	
Date of Loss:	16/12/2022	Nature of Claim:	OD	Claim No: 9071288042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJA1180H	Engine No:	DEM028557
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF45MN005986
Reg. Date:	28/07/2021 (Man. Year: 2020)	Odometer:	17414 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$163,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,265.00	15,446.00	17,819.00	53.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,734.00	6,304.00	13,430.00	68.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	52,999.00	21,750.00	31,249.00	58.96
- Excess (\$\$)	550.00	550.00	0.00	0.00
(\$\$)	52,449.00	21,200.00	31,249.00	59.58
+ GST 8.00/8.00% (\$\$)	4,195.92	1,696.00	2,499.92	59.58
Nett Amount (\$\$)	56,644.92	22,896.00	33,748.92	59.58

INSPECTION

Date of Assignment:	21/12/2022	
Date Inspected:	19/12/2022	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,377.00 FS	*1,901.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	393.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	293.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	51.00 FS	*40.08 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Scratched	151.00 FS	*120.40 FS
7	1		*FRONT BUMPER OUTER GRILLE HOLE COVER - RH	Not Necessary	54.00 FS	*- FS
8	1		*FRONT BUMPER GUIDE SECTION - RH	Necessary	41.00 FS	*32.24 FS
9	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
10	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
11	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
12	1		*FRONT BUMPER BRACKET	Not Necessary	154.00 FS	*- FS
13	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
14	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	266.00 FS	*- FS
15	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
16	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
17	1		*HORN BRACKET - RH	Not Necessary	33.00 FS	*- FS
18	1		*FRONT FENDER - RH	Buckled	1,227.00 FS	*981.60 FS
19	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	225.00 FS	*- FS
20	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	81.00 FS	*64.24 FS
21	1		*FRONT FENDER BRACKET - RH	Necessary	41.00 FS	*32.72 FS
22	1		*FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	Not Necessary	55.00 FS	*- FS
23	7		*FRONT FENDER RIVET	Necessary	27.00 FS	*21.28 FS
24	1		*FRONT FENDER BRACKET - RH	Not Necessary	36.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	262.00 FS	*209.60 FS
26	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	149.00 FS	*- FS
27	1		*FRONT WHEEL SPOILER	Cracked	82.00 FS	*65.12 FS
28	1		*FRONT WHEEL SPOILER END PLATE - RH	Not Necessary	40.00 FS	*- FS
29	1		*FRONT FENDER LEDGE COVER - RH LONG	Necessary	35.00 FS	*27.52 FS
30	1		*HEADLIGHT COVER - RH	Cut	49.00 FS	*38.64 FS
31	1		*BONNET	Bent	3,425.00 FS	*2,740.00 FS
32	1		*BONNET ATTACHMENT PARTS	Not Necessary	431.00 FS	*- FS
33	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
34	1		*FRONT FENDER LEDGE COVER - RH UPPER	Not Necessary	68.00 FS	*- FS
35	1		*BONNET STRIKER - RH	Not Necessary	56.00 FS	*- FS
36	1		*BONNET LOCK	Not Necessary	228.00 FS	*- FS
37	1		*FRONT PLENUM CHAMBER COVER	Not Necessary	108.00 FS	*- FS
38	1		*HEADLIGHT - RH	Broken	8,172.00 FS	*6,537.60 FS
39	1		*HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
40	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	45.00 FS	*- FS
41	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	45.00 FS	*- FS
42	1		*HEADLIGHT COMPENSATING PIECE	Not Necessary	47.00 FS	*- FS
43	1		*LIFT CYLINDER - RH	Not Necessary	231.00 FS	*- FS
44	1		*LIFT CYLINDER BRACKET	Necessary	7.00 FS	*5.44 FS
45	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
46	1		*LIFT CYLINDER CORRUGATED PIPE	Bent	53.00 FS	*42.00 FS
47	1		*LIFT CYLINDER WASH WATER RESERVOIR	Not Necessary	160.00 FS	*- FS
48	1		*LOCK CARRIER	Not Necessary	1,478.00 FS	*- FS
49	6		*READY-MIX COOLANT	Not Necessary	297.00 FS	*- FS
50	1		*RADIATOR AIR GUIDE - RH INNER	Not Necessary	51.00 FS	*- FS
51	1		*RADIATOR AIR GUIDE - RH OUTER	Not Necessary	19.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	2		*RADIATOR AIR GUIDE - LOWER / UPPER	Not Necessary	44.00 FS	*- FS
53	1		*AIR FILTER	Cracked	418.00 FS	*334.40 FS
54	1		*INTAKE AIR DUCT - RH	Not Necessary	25.00 FS	*- FS
55	1		*ENGINE AIR INTAKE HOSE - CENTER	Not Necessary	61.00 FS	*- FS
56	1		*FRONT FENDER BRACE - RH	Necessary	132.00 FS	*105.20 FS
57	2		*FRONT ALUMINIUM RIM - LH / RH	Scratched	2,584.00 FS	*2,067.20 FS
58	2		*FRONT ALUMINIUM RIM RUBBER VALVE	Necessary	8.00 FS	*5.92 FS
59	1		*FRONT WISHBONE LINK - RH LOWER	Not Necessary	605.00 FS	*- FS
60	1		*FRONT SUSPENSION GUIDE - RH LOWER	Not Necessary	1,057.00 FS	*- FS
61	1		*FRONT SUSPENSION GUIDE - RH UPPER	Not Necessary	575.00 FS	*- FS
62	1		*FRONT SUSPENSION GUIDE - RH UPPER	Not Necessary	575.00 FS	*- FS
63	1		*FRONT WHEEL BEARING HOUSING - RH	Not Necessary	1,070.00 FS	*- FS
64	1		*FRONT WHEEL BEARING HOUSING SWIVEL JOINT	Not Necessary	214.00 FS	*- FS
65	1		*FRONT WHEEL HUB	Not Necessary	499.00 FS	*- FS
66	1		*FRONT DOUBLE ANGLED BALL BEARING FLANGE	Not Necessary	273.00 FS	*- FS
67	1		*SUSPENSION FORKS - RH	Not Necessary	293.00 FS	*- FS
68	1		*COUPLING ROD	Not Necessary	129.00 FS	*- FS
69	1		*GAS SHOCK ABSORBER	Not Necessary	332.00 FS	*- FS
70	1		*TRACK ROD	Not Necessary	109.00 FS	*- FS
71	1		*TIE ROD END	Not Necessary	217.00 FS	*- FS
72	1		*LOCK CARRIER CONNECTING PLATE - RH	Not Necessary	241.00 FS	*- FS
73	1		*LOCK CARRIER CONNECTING PLATE - RH	Not Necessary	279.00 FS	*- FS
74	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
75	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
76	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
77	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
78	1		*LHS FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
79	1		*RHS FRONT TYRE (NPA)	Not Necessary	0.00 FS	*- FS
80	1		*SUNDRIES	Not Necessary	1,000.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	33,265.00	15,446.00
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	350.00	350.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM	New	1,400.00	0.00
4	TO CARRY OUT VACUUM AND REGAS FOR R1234	New	1,200.00	0.00
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	New	280.00	280.00
6	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY	New	2,800.00	0.00
7	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER, AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	1,500.00
8	TO RESPRAY FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS FRONT DOOR, DOOR HANDLE, RHS REAR DOOR AND RHS FRONT FENDER TOP SUPPORT	New	5,000.00	2,750.00
9	TO RENEW RHS FRONT RIM WITH TYRE AND LHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	560.00	560.00
10	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
11	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (\$\$)			19,734.00	6,304.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >