

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS22012739/UVY3E2**Date:** 10/01/2023REFERENCE

Insured/Claimant: TAN TENG WEE Policy No: MPC22P00265600
Date of Loss: 17/12/2022 Nature of Claim: OD Claim No: DMPC2200636H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGF4409P**
Make & Model: HONDA CROSSROAD, 1.8 (A) Engine No: R18A3011445
Reg. Date: 12/11/2008 (Man. Year: 2008) Chassis No: RT11008414
Colour: White Odometer: 182166 km
Engine Capacity: 1799 cc
Market Value/New Car Price: S\$8,500.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55Z R17 Rear Tyre Size: 225/55Z R17
Front Left Side: Tourador 7 mm Rear Left Side: Tourador 7 mm
Front Right Side: Tourador 7 mm Rear Right Side: Tourador 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,859.10	8,509.60	3,349.50	28.24
Miscellaneous Items	65.00	55.00	10.00	15.38
Labour	1,730.00	1,420.00	310.00	17.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,654.10	9,984.60	3,669.50	26.87
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	13,654.10	5,600.00	8,054.10	58.99
+ GST 7.00/7.00% (S\$)	955.79	392.00	563.79	58.99
Nett Amount (S\$)	14,609.89	5,992.00	8,617.89	58.99

INSPECTION

Date of Assignment: 21/12/2022 Present Location: SME Motor Pte Ltd (Kaki Bukit)
SME Motor Pte Ltd (Kaki Bukit)
Date Inspected: 21/12/2022 Inspected At: 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jan 2023)
Parts:	M1-SUV	HONDA CROSSROAD 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF4409P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET (WCP)	Buckled	750.00 F	*750.00 F
2	2		*FRT BONNET HINGE (WCP)	Bent	100.00 F	*100.00 F
3	1		*FRT BONNET LOCK (WCP)	Twisted	85.00 F	*85.00 F
4	1		*FRT BONNET INSULATOR (WCP)	Deformed	110.00 F	*110.00 F
5	8		*INSULATOR CLIP (WCP)	Necessary	20.00 F	*20.00 F
6	1		*FRT GRILLE (WCP)	Cracked	280.00 F	*280.00 F
7	1		*FRT GRILLE OUTER GARNISH (WCP)	Twisted	185.00 F	*185.00 F
8	6		*FRT GRILLE CLIP (WCP)	Necessary	15.00 F	*15.00 F
9	1		*FRT GRILLE CENTER LOGO (WCP)	Scratched	55.00 F	*55.00 F
10	1		*FRT BUMPER (CENTER) (WCP)	Distorted	980.00 F	*980.00 F
11	2		*FRT BUMPER RETAINER (WCP)	Bent	76.00 F	*76.00 F
12	10		*FRT BUMPER CLIP (WCP)	Necessary	25.00 F	*25.00 F
13	2		*FRT CORNER BUMPER (WCP)	Torn	500.00 F	*500.00 F
14	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	350.00 F	*350.00 F
15	2		*HEADLAMP (WCP)	Cracked	2,500.00 F	*1,600.00 F
16	2		*HEADLAMP LOWER BRACKET (WCP)	Cracked	150.00 F	*150.00 F
17	1		*HEADLAMP SUPPORT PANEL (WCP)	Bent	580.00 F	*580.00 F
18	1		*AIRCON CONDENSER (WCP)	Punctured	600.00 F	*600.00 F
19	1		*RADIATOR (WCP)	Holder Cracked	1,150.00 F	*1,150.00 F
20	1		*AIRCON MOTOR (WCP)	Not Necessary	230.00 F	*- F
21	1		*AIRCON MOTOR COWLING (WCP)	Not Necessary	95.00 F	*- F
22	1		*AIRCON FAN BLADE (WCP)	Not Necessary	55.00 F	*- F
23	1		*RADIATOR MOTOR (WCP)	Not Necessary	190.00 F	*- F
24	1		*RADIATOR MOTOR COWLING (WCP)	Not Necessary	135.00 F	*- F
25	1		*RADIATOR FAN BLADE (WCP)	Not Necessary	65.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	35.00 F	*- F
27	1		*RADIATOR SPARE TANK (WCP)	Not Necessary	95.00 F	*- F
28	1		*FRT RH FENDER (WCP)	Repair	380.00 F	*- F
29	1		*FRT RH FENDER PROTECTOR (WCP)	Not Necessary	135.00 F	*- F
30	1		*FRT RH FENDER INNER COWLING (WCP)	Not Necessary	135.00 F	*- F
31	10		*INNER COWLING CLIP (WCP)	Not Necessary	25.00 F	*- F
32	2		*WIPER CORNER GARNISH (WCP)	Not Necessary	170.00 F	*- F
33	1		*HEADLAMP SUPPORT TOP GARNISH (WCP)	Twisted	105.00 F	*105.00 F
34	8		*SUPPORT TOP GARNISH CLIP (WCP)	Necessary	20.00 F	*20.00 F
35	1		*AIRCON LIQUID PIPE (WCP)	Not Necessary	180.00 F	*- F
36	1		*AIRCON DISCHARGE PIPE (WCP)	Not Necessary	220.00 F	*- F

F=Franchise part.

Sub Total (\$)	10,781.00	7,736.00
+ Margin on L,N Items 10.00/10.00% (\$)	1,078.10	773.60
Total Parts (\$)	11,859.10	8,509.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	NUMBER PLATE (CRACKED)	40.00	35.00
2	1	RADIATOR COOLANT (NECESSARY)	25.00	20.00
Sub Total (S\$)			65.00	55.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	20.00
2	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
3	LABOUR CHARGE	New	700.00	600.00
4	SPRAY PAINTING	New	900.00	700.00
Gross Labour Cost (S\$)			1,730.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >