

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SP2001935747	Date of Loss:	06/12/2022
Vehicle Reg. No.:	SJC7938P	Driveable?	
Driver Age/Info:	54 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	UNIVERSE LEASING PTE LTD		
Driver:	LEE SIOW HUA		
Make/Model:	RENAULT FLUENCE, 1.5 D DCI 110 (A)	Vehicle Reg. Date:	19/02/2016
Vehicle Colour:	Brown/Grey	Chassis No:	VF1LZLF0E53997615
Engine No:	K9KN837D213511		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14 10 days		
Present Location:	DING AUTO PTE LTD (HQ)		

*Not Authorized
L1 Reg &
Memory After Paint
6x82000h*

COST OF CLAIMS	Amount
Parts	53,817.50
Miscellaneous Items	800.00
Labour	4,770.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	59,387.50
+ GST 7.00% (\$\$)	4,157.13
Nett Amount (\$\$)	63,544.63

This claim is handled by: **YAP WEI LIN**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: 143

Labour: Repairer's

Print Code:

Validity:

Further Info:

Version: 1.0 (Last Synchronised: 20 Dec 2022)

RENAULT FLUENCE 1.5 D DCI 110 (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List)

Ding Auto Pte Ltd/SJC7938P/20/12/2022 17:50

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	R ₁	0.00	0.00	*1,850.00 F	✓
2	1		*FRONT BUMPER BRACKET RH	R ₁	0.00	0.00	*120.00 F	✓
3	1		*FRONT BUMPER BRACKET LH	R ₁	0.00	0.00	*120.00 F	✓
4	1		*FRONT CTR BUMPER BRACKET	CM ₁	0.00	0.00	*85.00 F	✓
5	1		*FRONT BUMPER TOWING CAP	R ₂	0.00	0.00	*60.00 F	X
6	1		*FRONT BUMPER MOULDING RH	CM ₁	0.00	0.00	*300.00 F	✓
7	1		*FRONT BUMPER MOULDING LH	CM ₁	0.00	0.00	*300.00 F	✓
8	1		*FRONT BUMPER CTR MOULDING	CM ₁	0.00	0.00	*180.00 F	✓
9	1		*FRONT BUMPER IMPACT FOAM	CM ₁	0.00	0.00	*160.00 F	✓
10	1		*FRONT BUMPER LOWER SPOILER	CM ₁	0.00	0.00	*250.00 F	✓
11	1		*FRONT BUMPER GRILLE	CM ₁	0.00	0.00	*450.00 F	✓
12	1		*FRONT CTR GRILLE	CM ₁	0.00	0.00	*600.00 F	✓
13	1		*FRONT SUPPORT PANEL COMPLETE	R ₂	0.00	0.00	*1,200.00 F	✓
14	1		*GRILLE BADGE	CM ₁	0.00	0.00	*120.00 F	✓
15	1		*BONNET	R ₂	0.00	0.00	*1,050.00 F	✓
16	1		*BONNET HINGE RH	CM ₁	0.00	0.00	*380.00 F	✓
17	1		*BONNET HINGE LH	CM ₁	0.00	0.00	*380.00 F	✓
18	1		*BONNET LOCK	R ₁	0.00	0.00	*320.00 F	✓
19	1		*BONNET INSULATOR		0.00	0.00	*280.00 F	?
20	1		*FRONT FENDER RH	R ₁	0.00	0.00	*580.00 F	✓
21	1		*FRONT FENDER LH	R ₁	0.00	0.00	*580.00 F	✓
22	1		*FRONT FENDER INNER COVER RH		0.00	0.00	*285.00 F	?
23	1		*FRONT FENDER INNER COVER LH	R ₂	0.00	0.00	*285.00 F	X
24	1		*HEADLAMP ASSY RH	R ₂	0.00	0.00	*2,250.00 F	✓
25	1		*HEADLAMP ASSY LH	R ₂	0.00	0.00	*2,250.00 F	✓
26	1		*FOG LAMP ASSY RH		0.00	0.00	*720.00 F	?
27	1		*FOG LAMP ASSY LH		0.00	0.00	*720.00 F	?
28	1		*FOG LAMP COVER RH	CM ₁	0.00	0.00	*300.00 F	✓
29	1		*FOG LAMP COVER LH	CM ₁	0.00	0.00	*300.00 F	✓
30	1		*DAY LAMP ASSY RH	CM ₁	0.00	0.00	*340.00 F	✓
31	1		*DAY LAMP ASSY LH	CM ₁	0.00	0.00	*340.00 F	✓
32	1		*RADIATOR ASSY	R ₁	0.00	0.00	*800.00 F	✓
33	1		*RADIATOR AIR GUIDE RH	CM ₁	0.00	0.00	*120.00 F	✓
34	1		*RADIATOR AIR GUIDE LH	CM ₁	0.00	0.00	*120.00 F	✓
35	1		*CONDENSOR ASSY	R ₁	0.00	0.00	*1,100.00 F	✓
36	1		*INTERCOOLER ASSY		0.00	0.00	*1,450.00 F	?
37	1		*FAN SHROUD ASSY COMPLETE		0.00	0.00	*1,950.00 F	?
38	1		*FRONT BUMPER REINFORCEMENT	R ₁	0.00	0.00	*850.00 F	✓
39	1		*AIR FILTER HOUSING		0.00	0.00	*550.00 F	?
40	1		*AIR RESONATOR		0.00	0.00	*250.00 F	?
41	1		*AIR HOSE		0.00	0.00	*180.00 F	?
42	1		*AIR DUCT		0.00	0.00	*140.00 F	?
43	1		*FUSE BOX HOUSING		0.00	0.00	*350.00 F	?
44	1		*AIR-COND SUCTION HOSE		0.00	0.00	*450.00 F	?
45	1		*AIR-COND DISCHARGE HOSE		0.00	0.00	*320.00 F	?
46	1		*REAR DOOR MOULDING LH		0.00	0.00	*350.00 F	?
47	1		*DASHBOARD	T ₁	0.00	0.00	*4,200.00 F	✓

48	1	*DRIVER AIRBAG	<i>Burn</i>	0.00	0.00	*2,800.00 F	<i>✓</i>
49	1	*PASSENGER AIRBAG	<i>u</i>	0.00	0.00	*3,200.00 F	<i>✓</i>
50	1	*AIRBAG ECU	<i>na</i>	0.00	0.00	*1,550.00 F	<i>✓</i>
51	1	*STEERING COLUMN SPRING COMPLETE	<i>na</i>	0.00	0.00	*2,000.00 F	<i>✓</i>
52	1	*SEAT BELT ASSY RH	<i>na</i>	0.00	0.00	*1,220.00 F	<i>✓</i>
53	1	*SEAT BELT ASSY LH	<i>na</i>	0.00	0.00	*1,220.00 F	<i>✓</i>
54	1	*FRONT WINDSCREEN - GLASS	<i>CM</i>	0.00	0.00	*1,700.00 F	<i>✓</i>
55	1	*FRONT WINDSCREEN - MOULDING	<i>na</i>	0.00	0.00	*300.00 F	<i>X</i>
56	1	*WASHER TANK	<i>na</i>	0.00	0.00	*240.00 F	<i>✓</i>
57	1	*FRONT INDICATOR LAMP ASSY RH	<i>ASP</i>	0.00	0.00	*380.00 F	<i>X</i>
58	1	*FRONT INDICATOR LAMP ASSY LH	<i>u</i>	0.00	0.00	*380.00 F	<i>X</i>
59	1	*PARKING SENSOR X 4PCS (EACH \$400/PC)	<i>3</i>	0.00	0.00	*1,600.00 F	<i>✓</i>
60	1	*HEADLAMP MODULE RH		0.00	0.00	*900.00 F	<i>?</i>
61	1	*HEADLAMP MODULE LH		0.00	0.00	*900.00 F	<i>?</i>
62	1	*HORN - HIGH PITCH		0.00	0.00	*100.00 F	<i>?</i>
63	1	*HORN - LOW PITCH		0.00	0.00	*100.00 F	<i>?</i>

F=Franchise part.

Sub Total (\$\$)	48,925.00
+ Margin on L,N Items 10.00% (\$\$)	4,892.50
Total Parts (\$\$)	53,817.50

Ding Auto Pte Ltd/SJC7938P/20/12/2022 17:50. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT GRILLE, INNER COVER & GARNISH PANEL CLIPS	250.00	✓
2	1	HEADLAMP MODULE & ECU - REPROGRAMMING & CALIBRATION	550.00	300

Sub Total (S\$) 800.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,800.00	800
2	SPRAY PAINT - FRT BUMPER, BONNET, FRT FENDER X2, FRT DOOR X2, REAR DOOR LH & SUPPORT PANEL	New	1,800.00	1200
3	REMOVE & REFIT - DASHBOARD COMPONENTS	New	250.00	✓
4	REMOVE & REFIT - SEAT BELT COMPONENTS (X2)	New	250.00	1200
5	REMOVE & REFIT - FRT WINDSCREEN GLASS	New	180.00	1200
6	ALIGN HEADLAMP/FOG LAMP/ DAY LAMP & TEST WIRING	New	180.00	300
7	ALIGN PARKING SENSOR & TEST WIRING	New	150.00	600
8	REFILL - RADIATOR COOLANT	New	80.00	500
9	REFILL - AIRCOND GAS	New	80.00	✓

Gross Labour Cost (S\$) 4,770.00

Ding Auto Pte Ltd/SJC7938P/20/12/2022 17:50. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >