

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012754/AVY3M4**Date:** 08/03/2023**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00128282201

Claimant Vehicle No : SMC8588Z **Insured Vehicle No :** SFV3369E

Date of Loss: 12/12/2022 Nature of Claim: TP Claim No: SNM22D208953/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC8588Z**

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8409991

Reg. Date: 22/06/2018 (Man. Year: 2018) Chassis No: ZYX102113798

Colour: Silver Odometer: 64116 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R18 Rear Tyre Size: 215/55 R18

Front Left Side: PETLAS 6 mm Rear Left Side: PETLAS 6 mm

Front Right Side: PETLAS 6 mm Rear Right Side: PETLAS 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,392.42	2,382.80	5,009.62	67.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	1,110.00	2,270.00	67.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,772.42	3,492.80	7,279.62	67.58
Approved Total (Overridden) (\$\$)		2,800.00		
Nett Amount (\$\$)	10,772.42	2,800.00	7,972.42	74.01

INSPECTION

Date of Assignment: 21/12/2022

Date Inspected: 22/12/2022 Inspected At: AUTOMOBILE HUB ENTERPRISE
1 KAKI BUKIT AVENUE 6
#02-11 AUTOBAY
SINGAPORE 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2023)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC8588Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	855.10 FL	*855.10 FL
2	2		*REAR BUMPER SIDE HOLDER @112.20	Necessary	224.40 FL	*224.40 FL
3	2		*REAR BUMPER SIDE GRILLE @187.00	Not Necessary	374.00 FL	*- FL
4	2		*REAR BUMPER SIDE GRILLE REFLECTOR @59.00	Not Necessary	118.00 FL	*- FL
5	1		*REAR BUMPER TOW COVER	Deformed	27.70 FL	*27.70 FL
6	1		*REAR BUMPER LOWER GARNISH	Deformed	465.10 FL	*465.10 FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	352.70 FL	*352.70 FL
8	2		*REAR BUMPER UNDERCOVER @189.20	Not Necessary	378.40 FL	*- FL
9	1		*REAR BUMPER LOWER GARNISH REFLECTOR	Cracked	145.40 FL	*145.40 FL
10	1		*REAR END PANEL	Not Necessary	731.40 FL	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	347.40 FL	*- FL
12	1		*REAR END PANEL ANTENNA SENSOR	Not Necessary	106.90 FL	*- FL
13	1		*TAILGATE	Repair	1,112.50 FL	*- FL
14	1		*TAILGATE LOCK	Not Necessary	389.40 FL	*- FL
15	1		*TAILGATE LOCK COVER	Not Necessary	29.40 FL	*- FL
16	1		*TAILGATE LOCK STRIKER	Not Necessary	105.50 FL	*- FL
17	1		*TAILGATE WEATHERSTRIPE	Not Necessary	371.40 FL	*- FL
18	1		*TAILGATE INNER PULL POCKET	Not Necessary	38.40 FL	*- FL
19	1		*TAILGATE GLASS MOULDING	Not Necessary	158.40 FL	*- FL
20	1		*TOYOTA LOGO	Not Necessary	72.20 FL	*- FL
21	1		*CHR WORDING	Not Necessary	55.60 FL	*- FL
22	1		*HYBRID EMBLEM	Not Necessary	121.40 FL	*- FL
23	1		*REAR EXHAUST PIPE	Not Necessary	987.90 FL	*- FL
24	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	45.00 FL	*- FL
25	1		*REAR EXHAUST PIPE GASKET	Not Necessary	45.40 FL	*- FL
26	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	110.90 FL	*- FL
27	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
28	1		*REAR BUMPER LOWER SPOILER	Damaged	1,000.00 FS	*600.00 FS
29	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
31	1		*TAILGATE GLASS SEALANT	Not Necessary	60.00 FS	*- FS
32	2		*REVERSE SENSOR	Damaged	375.00 FS	*200.00 FS
					Sub Total (\$\$)	9,334.90 2,900.40
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,942.48 517.60
					Total Parts (\$\$)	7,392.42 2,382.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,200.00	500.00
2	SPRAY PAINTING	New	1,200.00	500.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	0.00
5	TO REMOVE UPHOLSTERY	New	150.00	30.00
6	TO TRANSFER TAILGATE FITTINGS	New	150.00	0.00
7	TO REMOVE TAILGATE GLASS	New	180.00	0.00
8	TO REMOVE REVERSE SENSOR	New	100.00	50.00
9	TO REMOVE REAR CAMERA	New	100.00	0.00
10	TO REMOVE REAR VIDEO RECORDER	New	100.00	0.00
Gross Labour Cost (S\$)			3,380.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >