

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22012755/TWY3E2**Date:** 13/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00015772100

**Claimant Vehicle
No :** SMR6103Z**Insured Vehicle
No :** SLX9836C

Date of Loss: 17/12/2022

Nature of Claim: TP

Claim
No: SNM22D209110/C02/IRENEDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMR6103Z**

Make & Model: NISSAN SYLPHY, 1.6 CVT (A)

Engine No: HR16943461C

Reg. Date: 15/01/2020 (Man. Year: 2019)

Chassis No: MNTBBAB17Z0036158

Colour: Grey

Odometer: 21828 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size: 195/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,350.20 | 654.15 | 1,696.05 | 72.17 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 880.00 | 400.00 | 480.00 | 54.55 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 3,230.20 | 1,054.15 | 2,176.05 | 67.37 |
| Approved Total (Overridden) (S\$) | | 850.00 | | |
| (S\$) | 3,230.20 | 850.00 | 2,380.20 | 73.69 |
| + GST 7.00/7.00% (S\$) | 226.11 | 59.50 | 166.61 | 73.69 |
| Nett Amount (S\$) | 3,456.31 | 909.50 | 2,546.81 | 73.69 |

INSPECTION

Date of Assignment: 21/12/2022

Date Inspected: 22/12/2022 Inspected At:

Dickson Auto Care Centre Pte Ltd (HQ)
29 Ubi Road 4, Dickson Auto Centre
Singapore 408619

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** XinYu

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 13 Mar 2023) |
| Parts: | 143 | NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMR6103Z) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|---------------|------------|------------|
| 1 | 1 | | *FRONT BUMPER | Deformed | 693.50 F | *693.50 FL |
| 2 | 10 | | *FRONT BUMPER CLIPS | Necessary | 100.00 FS | *30.00 FS |
| 3 | 1 | | *FRONT BUMPER LH SIDE RETAINER | Not Necessary | 55.60 F | *- FL |
| 4 | 1 | | *FRONT BUMPER LH FOG LAMP | Not Necessary | 353.10 F | *- FL |
| 5 | 1 | | *FRONT BUMPER LH FOG LAMP COVER | Not Necessary | 143.10 F | *- FL |
| 6 | 1 | | *FRONT LH HEADLAMP | Not Necessary | 1,004.90 F | *- FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|-----------------|---------------|
| Sub Total (\$\$) | 2,350.20 | 723.50 |
| - List Item Discount on L Items 0.00/10.00% (\$\$) | 0.00 | 69.35 |
| Total Parts (\$\$) | 2,350.20 | 654.15 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|---------------|---------------|
| Labour Items | | | | |
| 1 | TO REMOVE & REFIX FRONT HEADLAMP & REFOCUS | New | 80.00 | 0.00 |
| 2 | TO REMOVE & REFIX ALL DAMAGED PARTS & PANELS | New | 400.00 | 200.00 |
| 3 | TO PAINT NEW PARTS & PANELS | New | 400.00 | 200.00 |
| Gross Labour Cost (\$\$) | | | 880.00 | 400.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >